THE CHURCH OF JESUS CHRIST OF LATTER-DAY SAINTS

EAGLE ID FM GROUP P.O. Box 609 Eagle, Idaho 83616-0609 Phone: 208-939-2108 Facsimile: 208-939-2445

May 23, 2014

Department of Environmental Quality Division of Radiation Control 168 N 1950 West PO Box 144850 Salt Lake City, UT 84114-4850

In fulfillment of the requirements of 10 CFR 31.5 (c) 8, we hereby notify you that on May 12, 2014 we transferred the self-luminous exit signs listed on the attached spreadsheet to SRBT, 320-140 Boundary Rd., Pembroke, Ontario, K8A 6W5, Canada with CNSC License #NSPFOL-12.00/2013. As required, for each sign listed on the spreadsheet, we include the name of the manufacturer, model number, and serial number.

If you should have any questions, please contact Tamara Shipley Administrative Assistant for the Eagle Idaho FM Group 208-939-2108

Sincerely,

amara shiplus

Tamara Shipley

Encl.

isolite

DOT Hazmat Training and Acknowledgement FOR RETURN OF SELF-LUMIOUS EXIT SIGNS

- Self-Luminous EXIT signs are illuminated with internal light sources powered by tritium gas. \triangleright Tritium gas is a radioactive isotope of hydrogen. For this reason, Federal Regulations require that any person shipping this product must have training sufficient to comply with US Department of Transportation regulations in the Code of Federal Regulations #49 Part 172.
- To receive this training, the shipper must read, understand and perform the following steps. ≽ Place a check mark at each step after complete. Sign and date this form. Upon receipt of this completed form we will provide you with the RMA Number required for the return of these signs along with complete shipping instructions.
- Keep this completed form in your files for at least 3 years in case of regulatory inspection. ⋟
 - The EXIT signs are to be shipped as excepted packages for radioactive instruments and articles (49CFR 173.424). No special packaging is necessary.
 - A sturdy cardboard box, plastic drum, or metal drum will be sufficient to ship the signs because they all meet the general package design requirements of 49CFR173,410. The package must withstand normal conditions of transport without any deterioration. The container must be clean and never have been near other radioactive material so that the shipper can be sure that there is no radioactive contamination on the outside of the container.
 - You must ensure that the active materials (the glowing inner tubes) are completely enclosed by non-active components (the plastic sign housing). Therefore, each sign must be visually inspected to ensure that it is not crushed or punctured in a way that might cause an inner light tube to be broken.
 - Each sign must contain less than 20 curies of tritium (see the sign's rear label). The total amount of curies to be placed into each container must be less than 100 Ci. (Add up the curie content of each sign as you put them into the container.)
 - If a transportation incident occurs, you must report the incident to the USDOT per 49 CFR 171.15 and 171.16.
 - Read and understand the "Packaging Instructions" and follow each step exactly.

2436092877 MTS Order Number

Name (Printed)

Tamara Shipluj ame (Printed) Camana Shipluy

EWS Purchase Order Number

Eagle ID FM Group Company

4/30/IU

If you have any questions, call Isolite at 800-888-5483.

SERIAL NUMBER SPREADSHEET

Company Name	Eagle, ID FM Group	Date	4130/2014
Address 1	TOP W State St.	Isolite RMA #	
Address 2		EWS Order #	
Address 3		MTS Order #s	2430092877
City/State	Eacle, ID	Contact Name	Tamara Shiple,
Zip/Post Code	83687	Contact Phone	Tamara Shipley 208-939 - 2108
Country	USA	Contact FAX	
<u></u>		Contact E-mail	Shipley TF @ LDSChur

	Manufacturer Name	Model No.	Serial No.	Manuf Da Month		Activity Include "Ci" or "TBq"
1	SRB TICH	u 20	603200	10	89	20 ci
	SRB Tech	4 20	503211	10	89	DOCI
3	SRB Tech	U 20	503222	10	89	20 ci
4	SRB TICH	U 20	563210	10	89	200
5	SRB Tech	U 20	503217	10	89	JUCI
6	SRB TICH	4 20	503218	10	89	20 ci
7	SRB Tich	420	503219	10	89	20ci
8	SRB Tuch	U 20	503213	10	89	20ci
9	SRB JICN	U 20	503215	10	89	ZOCI
10	SRB TICH	4 20	503216	10	89	20 ci
11	SRB Tech	U 20	503212	10	89	soci
12	SRB TICN	missing	503221	10	89	20 ci
13	SRB Tech	420	603223	10	89	20 ci
14	missing	laber missing	labol missing	missing	missing	missing
15	P	,	,	, i	· ·	

*The above information should be on the signs labels. If any information on the sign is missing please fill in the fields with "missing" or "illegible", etc. Please print clearly. A double sign is counted as "TWO" signs---not "ONE" Please make note of this.

Once we have received and processed this information an RMA number will be issued.

If you have more signs that this form holds, please copy additional pages and filling all necessary information.