

Letter to N. C. Moseley from Carolina Power and Light Company dated April 11, 1975.

DISTRIBUTION:

H. D. Thornburg, IE

IE:HQS (5)

Office of Standards Development

Central Files

Division of Reactor Licensing (13)

J. Rizzo, OMIPC

PDR

Local PDR

NSIC

TIC

Chief, Regulatory News Branch, OIS, HQs

50-261

Reply to IEB - 75-03

A0  
(2)



Carolina Power & Light Company

April 11, 1975

FILE: NG-3513 (R)

SERIAL: NG-75-524

Mr. Norman C. Moseley, Director  
U. S. Nuclear Regulatory Commission  
Region II, Suite 818  
230 Peachtree Street, N. W.  
Atlanta, Georgia 30303

Dear Mr. Moseley:

H. B. ROBINSON NO. 2  
LICENSE NO. DPR-23  
BULLETIN IE 75-03  
INCORRECT OPERATION OF ASCO SOLENOID VALVES

In accordance with IE Bulletin No. 75-03, an investigation at H. B. Robinson No. 2 revealed no solenoids of series 8300C, 8302C types F, U, RF or RU in the primary or any other safety related system.

Three valves of this series were found on the secondary system in nonsafety related applications, and five of the subject valves and nine repair kits are presently in stock. These stock items were marked for use in only nonsafety related applications April 7, 1975, and will be controlled in accordance with the Robinson Continuing Quality Assurance Plan.

Yours very truly,

E. E. Utley  
Vice President  
Bulk Power Supply

DBW:pn

cc: Mr. N. B. Bessac  
Mr. P. W. Howe  
Mr. R. E. Jones  
Mr. J. B. McGirt  
Mr. D. B. Waters