

MATERIAL TRANSPORTED HEREWITH CONTAINS 2.700 ELFORMATION UNITED STATES NUCLEAR REGULATORY COMMISSION

REGION II				
101 MARIETTA ST., N.W., SUITE 3100				
ATLANTA, GEORGIA 30303				

<b>S-</b> F2_	- 08	60	
Copy	cf		Copies
<u> </u>	Page		

This Decuration is not to be reproduced without specific approval of IS:II

## MAY 1 4 1980

Report No. 50-261/80-9

Docket No. 50-261

License No. DPR-23

Licensee: Carolina Power and Light Company 411 Fayetteville Street Raleigh, NC 27602

Facility Name: H. B. Robinson 2

Inspection at: H. B. Robinson Nuclear Plant, Hartsville, SC

Inspection conducted: April 21-25, 1980

Date of Last Physical Security Inspection Visit: January 23-25, 1980

Type of Inspection: Upannounced Physical Security

Inspectors: Δ Security Inspector Howell, Physical Security Inspector 5-14-80 Approved by: Gillespie, Acting Section Chief, Safeguards Branch

Inspection Summary

8 0071 50

Areas Inspected: Included review of the licensee's security program audit, vital and protected area barriers, security lighting, communications, detection aids, assessment aids, power supply, and locks, keys, and combinations.

The inspection involved 60 inspector hours on site by two NRC inspectors. Ten inspection hours were accomplished during offshift periods.

Results: The licensee was found to be in compliance with NRC requirements within the nine areas examined during the inspection except for the following four items:

- 1. Physical Barrier Insecure grates and hatches provided unauthorized access into a vital area (50-261/80-09-01).
- 2. Detection Aids An exit door in a vital area was not equipped with an intrusion detection alarm (50-261/80-09-02).
- 3. Detection Aids Tamper indicating capability could not be demonstrated in a protected area alarm system (50-261/80-09-03).
- Assessment Aids Operable CCTV equipment dedicated to surveillance of a vital area did not provide an acceptable level of observation (50-261/80-09-04).

MATERIAL TRANSMITTED HEREWITH 107CONTAINS 2.702 MIEGDIARTION