U.S. NUCLEAR REGULATORY COMMISSION (07-2012) 10 CFR 2:201 SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION							
1. LICENSEE/LOCATION INSPECTED: 2. NRC/REGIONAL OFFICE							
American Engineering Testing, Inc. 550 Cleveland Avenue North St. Paul, MN 55114 REPORT NUMBER(S) 2014-001			Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352				
3. DOCKET NUMBER(S		4. LICENSE NUMBER	R(S)	5. DATE(S) OF INSPECTIO	DN		
030-34637		22-20271-02		June 19, 2014			
LICENSEE: The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows: Image: Procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows: Image: Procedures and the inspection findings, no violations were identified. Image: Provious violation(s) closed. Image: Provious violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, to exercise discretion, were satisfied. Image: Provide violation(s) were discussed involving the following requirement(s):							
 During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited in accordance with NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11. (Violations and Corrective Actions) 							
Statement of Corrective Actions I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken,							
	ance will be achieved). I understand th PRINTED NAME	at no turther written	response to NRC will be require SIGNATURE	ed, unless specifically req	uested.		
TITLE LICENSEE'S REPRESENTATIVE	PRIN IED NAME		SIGNATURE		DATE		
NRC INSPECTOR	Deborah A. Piskura, Health Physi	cist	Delion Att	Ane	2/19/2014		
BRANCH CHIEF	Aaron T. McCraw, Chief, MIB		J-MC		6 26 14		

NRC FORM 591M PART 3			U.S. NU	CLEAR REGULATORY COMMISSION				
(07-2012) 10 CFR 2.201	D	ocket File Info		JLEAR REGULATORT GOMMOUTIN				
SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION								
1. LICENSEE/LOCATION INSPECT	ED:		2. NRC/REGIONAL OFFICE					
American Engineering Te			Region III					
550 Cleveland Avenue No	orth		U. S. Nuclear Regulatory Commission					
St. Paul, MN 55114			2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352					
REPORT NUMBER(S) 2014-(001			-				
3. DOCKET NUMBER(S)		4. LICENSE NUMBER(S	S)	5. DATE(S) OF INSPECTION				
030-34637		22-20271-02		June 19, 2014				
6. INSPECTION PROCEDURES US	ED	7. INSPECTION FOCUS AREAS						
87121		03.01- 03.07						
SUPPLEMENTAL INSPECTION INFORMATION								
1. PROGRAM CODE(S)	2. PRIORITY	3. LICENSEE CONTAC	Τ	4. TELEPHONE NUMBER				
03320	1	Greg Owens, RS	0	(715) 359-3534				
✓ Main Office Inspec	tion	Next Inspection	Date: June 201	5				
Field Office Inspec	tion							
Temporary Job Site Inspection								
		PROGRAM SC	COPE					
This large multi-site engineering and consulting company employed 400 individuals (20 radiographers and 4 assistants) and offered NDE services (isotope, mag particle, ultrasound, etc.). The majority of the licensee's activities were conducted under various Agreement State licenses (Florida, Minnesota, and Wisconsin). The NRC-licensed activities authorized under this license were limited to two field stations in Gary, Indiana, and Beresford, South Dakota. Radiography was performed daily at temporary job sites using 2-man teams. All of the radiographic operations were conducted at temporary job sites. No radiography (i.e., on the business property) was conducted under the provisions of this NRC license.								
This inspection at the corporate office was limited to a review of selected records and interviews with licensee personnel. The inspector reviewed documents pertaining to utilization logs, radiographers' training and certifications, operating and emergency procedures, radiation safety program audits, and NRC Regulations. Each field station maintained its records of dosimetry, equipment maintenance, radiographers audits, etc.								