

ACCELERATED DOCUMENT DISTRIBUTION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9309280261 DOC. DATE: 93/09/20 NOTARIZED: NO DOCKET #
 FACIL: 50-261 H.B. Robinson Plant, Unit 2, Carolina Power & Light Co 05000261
 AUTH. NAME AUTHOR AFFILIATION
 WATERS, D.B. Carolina Power & Light Co.
 RECIP. NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: Provides info re disassembly of Check Valves SI-875, A, B & C to be performed at Unit 2. Future insps will be performed per GL-89-04 requirements.

DISTRIBUTION CODE: A047D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1
 TITLE: OR Submittal: Inservice/Testing/Relief from ASME Code

NOTES:

	COPIES			COPIES
RECIPIENT ID CODE/NAME	LTTR	ENCL	RECIPIENT ID CODE/NAME	LTTR ENCL
PD2-1 LA	1	0	PD2-1 PD	1 1
MOZAFARI, B	2	2		
INTERNAL: AEOD/DSP/ROAB	1	1	NRR/DE/EMEB	1 1
NRR/EMCB	1	1	NUDOCS-ABSTRACT	1 1
OC/LFDCB	1	0	OGC/HDS2	1 0
<u>REG FILE</u> 01	1	1	RES/DSIR/EIB	1 1
EXTERNAL: EG&G BROWN, B	1	1	EG&G RANSOME, C	1 1
NRC PDR	1	1	NSIC	1 1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
 ROOM P1-37 (EXT. 504-2065) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 16 ENCL ~~13~~ 0



Carolina Power & Light Company

ROBINSON NUCLEAR PLANT
POST OFFICE BOX 790
HARTSVILLE, SOUTH CAROLINA 29551

SEP 20 1993

Robinson File No.: 14506

Serial: RNP/93-2251

United States Nuclear Regulatory Commission
ATTENTION: Document Control Desk
Washington, DC 20555

H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2
DOCKET NO. 50-261/LICENSE NO. DPR-23
DISASSEMBLY OF SAFETY INJECTION SYSTEM CHECK VALVES

Gentlemen:

The purpose of this letter is to provide information regarding the disassembly of Check Valves SI-875 "A", "B", and "C" which will be performed at the H. B. Robinson Nuclear Plant, Unit No. 2.

Carolina Power & Light Company's letter, dated December 28, 1992, described testing which was performed on these valves during the last refueling outage, and noted that, additionally, Valve SI-875C was disassembled. As discussed in a conference call with the NRC on September 3, 1993, for future inspections, the In-Service Testing Program has been modified to provide for disassembly and inspection of the SI-875 "A", "B", and "C" Valves in accordance with the guidance of Generic Letter 89-04.

Questions regarding this matter may be referred to Mr. Jan S. Kozyra at (803) 383-1872.

Very truly yours,

David B. Waters
Manager

Regulatory Affairs Section

JSK:lst

cc: Mr. S. D. Ebner
Mr. B. L. Mozafari
Mr. W. T. Orders

ADD 1/0

9309280261 930920
PDR ADOCK 05000261
P PDR