

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8011120437 DOC. DATE: 80/11/05 NOTARIZED: NO DOCKET # 05000261  
 FACIL: 50-261 H. B. Robinson Plant, Unit 2, Carolina Power and Light 05000325  
 50-325 Brunswick Steam Electric Plant, Unit 1, Carolina Power 05000324  
 50-324 Brunswick Steam Electric Plant, Unit 2, Carolina Power 05000324

AUTH. NAME UTLEY, E.E. AUTHOR AFFILIATION Carolina Power & Light Co.  
 RECIP. NAME EISENHUT, D.G. RECIPIENT AFFILIATION Division of Licensing

SUBJECT: Submits info re shift staffing in response to NRC 800731 ltr transmitting interim criteria.

DISTRIBUTION CODE: A001S COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1  
 TITLE: General Distribution for after Issuance of Operating License

NOTES:

	RECIPIENT ID CODE/NAME		COPIES LTR ENCL		RECIPIENT ID CODE/NAME		COPIES LTR ENCL
ACTION:	VARGA, S. 04		13		IPPOLITO, T. 04		13
INTERNAL:	D/DIR, HUM FAC08		1		I&E 06		2
	NRC PDR 02		1		OELD 11		1
	OR ASSESS BR 10		1		REG FILE 01		1
EXTERNAL:	ACRS 09		16		LPDR 03		1
	NSIC 05		1				

NOV 13 1980

TOTAL NUMBER OF COPIES REQUIRED: LTR 51 ENCL 0



Carolina Power & Light Company

November 5, 1980

File: NG-3514(B&R)

Serial No.: NO-80-1648

Mr. Darrell G. Eisenhut, Director  
Division of Licensing  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

H. B. ROBINSON STEAM ELECTRIC PLANT UNIT NO. 2  
DOCKET 50-261, LICENSE NO. DPR-23  
BRUNSWICK STEAM ELECTRIC PLANT UNIT NOS. 1 AND 2  
DOCKET 50-325 AND 324, LICENSE NOS. DPR-71 AND 62  
INTERIM CRITERIA FOR SHIFT STAFFING

US NRC  
DISTRIBUTION SERVICES  
BRANCH

1980 NOV 10 AM 10 56

RECEIVED DISTRIBUTION  
SERVICES UNIT

Dear Mr. Eisenhut:

We have reviewed your July 31, 1980 letter transmitting interim criteria for shift staffing and have assessed the compliance of each of our operating units to these criteria. The response of each plant is summarized below.

H. B. Robinson

The Robinson Plant is not now in conformance with the interim guidelines for all shifts. While each shift always has the required total number of licensed personnel, on some shifts this complement is composed of a shift supervisor with an SRO and three ROs instead of the guideline staffing of two SROs and two ROs. Efforts are underway to alleviate this shortage of SROs, but because of the uncertainty of the criteria for qualification to take SRO examinations, CP&L believes it may not be able to reach full compliance with these interim guidelines at Robinson prior to July 1, 1982. CP&L is committed to achieving compliance with the guidelines as quickly as possible.

Brunswick

The Brunswick Plant is currently operating in full compliance with the interim guidelines and plans to continue to do so.

Yours very truly,

E. E. Utley  
Executive Vice President  
Power Supply and  
Engineering & Construction

CSB/jc (068-515)

cc: Mr. T. A. Ippolito  
Mr. Steven A. Varga

A001  
S/10

8011120437

411 Fayetteville Street • P. O. Box 1551 • Raleigh, N. C. 27602