

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:
Worthington, Lenhart & Carpenter, Inc.
200 Pronghorn Street
Casper, Wyoming 82601

2. NRC/REGIONAL OFFICE

U.S. Nuclear Regulatory Commission
Region IV, 1600 East Lamar Blvd
Arlington, Texas 76011-4511

REPORT NO: 2013-001

3. DOCKET NUMBER
030-32144

4. LICENSE NUMBER
49-27067-01

5. DATE OF INSPECTION
November 4-20, 2013

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.*
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy to exercise discretion, were satisfied.
- Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

- 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

2. Previous violation(s) closed.*

The corrective actions were reviewed during this inspection & the inspector recommends closure of two 10/2008 violations:

- 1) The licensee did not provide recurrent training for its hazmat employees which satisfied the requirements in Subpart H to 49 CFR Part 172, between the years 2000-2004; and
- 2) The licensee failed to conduct annual reviews of its radiation protection program for the years 2003-2008.

Violation for licensee possessed and used byproduct material at the Pinedale, Wyoming location, a location not authorized by the license. This was immediately corrected by license amendment issued 12/2008. The inspector recommends this violation remain open until an inspection can be conducted at this use location.

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Latischa M. Hanson	<i>Latischa M. Hanson</i>	November 21, 2013
BRANCH CHIEF	<i>[Signature]</i>		Sept. 18, 2013

Non-Public Sensitive - Security-Related

Public

Non-Sensitive