	January S. Commission of the C			
NRC FORM 591M PART 1 (4-2008) 10 CFR 2-201		U.S. NUCLE	AR REGULATORY COMMISSION	
SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION				
LICENSEE/LOCATION INSPECTED: TechCorr USA, LLC		2. NRC/REGIONAL OFFICE		
Temporary job site locations in Gillette, Wyoming Field office: 305 Commerce Street, Gillette, Wyoming		U.S. Nuclear Regulatory Commission Region IV, 1600 East Lamar Blvd		
REPORT NO: 2014-002		Arlington, Texas 76011-4511		
3. DOCKET NUMBER	4. LICENSE NUMBER		5. DATE O	F INSPECTION
030-37457	42-29261-01		Septe	ember 26 – October 9, 2014
The inspection was an examination of the activit Regulatory Commission (NRC) rules and regula procedures and representative records, interview 1. Based on the inspection findings, not 2. Previous violation(s) closed. 3. The violations(s), specifically descriptions identified non-experitive, and commissions.	tions and the conditions of the way with personnel, and observed in the conditions were identified bad to you by the inspects	of your ilcense. The inspections by the inspections.	ection consisted tor. The inspecti	of selective examinations of ion findings are as follows:
identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy to exercise discretion, were satisfied. Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):				
4. During this inspection certain of your cited. This form is a NOTICE OF VIC (Violations and Corrective Actions) 10 CFR 34.35(h) states that "The license labeled, marked, and accompanied with Contrary to the above, on October 7, 201 with both labels completely illegible. Specentaining radionuclide, activity, and tran	e may not transport licens per may not transport licens per populate shipping pape 4, the licensee transports diffication the licensee transports	sed material unless the need in accordance with re	rdance with 10 C naterial is packag gulations set out	ged, and the package is in 10 CFR Part 71."
This is a Severity Level IV violation (Example 6.8.d.4). As part of the short term corrective action, the corporate radiation safety officer instructed the site radiation safety officer (RSO) to retrain the authorized users on the importance of ensuring that radiography cameras are labeled appropriately and contain regulatory required information. Long term corrective actions includes: 1) posting signs on the vault door and inside the vault reminding users to verify that the labels are in place before transporting cameras, 2) all users are to ensure that cameras comply with the regulation before logging out a camera, and 3) the site RSO will be checking cameras frequently to ensure that the labeling is up to date.				
Licensee's S hereby state that, within 30 days, the actions described actions is made in accordance with the date when full compliance will be achieved). I utilitie Printed Nam	requirements of 10 CFR 2 indenstand that no further	sector will be taken to co	react the violation	ns identified. This statement of rective steps which will be taken, unless specifically requested. Date
LICENSEE'S Jeffrey S. Spea	ırman	Seam		10/27/14
RC INSPECTOR Roberto J. Torre	s, M.S.	ZAL BIG		October 27, 2014
RANCH CHIEF Jack E. White	ten	AHIII		October 27, 2014
FORM 591M PART 1 (Rev. by RIV 12/11)	1	SADNAS IND BURNANCH	FORMS/591M FC	RMS\Part1 Publicly Available.doc
Non-Public Sensitive - Securi	ty-Related	X	Public	X Non-Sensitive