

LICENSEE EVENT REPORT EVALUATION FORM

Page 1 of 3

EVENT CLASS: LAS - LOST, ABANDONED, STOLEN MATERIAL**LICENSEE / REPORTING PARTY INFORMATION:**

Licensee/Reporting party name:	Schlumberger Technology Corporation		
License number :	42-00090-03		
Docket number :	030-06388		
Licensee's City of record :	Sugarland		
Licensees State of record :	Texas		
NRC regulated?	yes	If so, what Region?	IV
Working under reciprocity?	no		

EVENT INFORMATION:

In what City and State did the event occur?	Offshore Federal waters (OCS-G 25142)
Event date :	6/28/2013
Discovery date :	6/28/2013
Report date :	7/16/2013
Agreement State reportable?	no
NRC reportable?	yes
Reporting regulation :	10 CFR 39.77(d)
NMED Item Number or ADAMS ML :	ML13207A409

ADDITIONAL PARTIES INVOLVED:

Name :	ENI US Operating Company
License number :	N/A
City :	
State :	

LICENSEE EVENT REPORT EVALUATION FORM

EVENT CLASS: LAS - LOST, ABANDONED, STOLEN MATERIAL

CONSULTANT INFORMATION (if any):

Consultant name :	N/A
Company :	
Who hired consultant?	

DEVICE INFORMATION:

Manufacturer :	Logging tool
Model number :	N/A
Serial number :	

RADIATION SOURCE INFORMATION:

Isotope :			Cesium-137
Activity :			1.7 curies
Manufacturer :			AEA Technologies
Model number :			GGLS-DA
Serial number :			A2584

LICENSEE EVENT REPORT EVALUATION FORM

EVENT CLASS: LAS - LOST, ABANDONED, STOLEN MATERIAL

NARRATIVE EVENT DESCRIPTION:



1 source was abandoned downhole after becoming stuck in a well in offshore Federal waters (Green Canyon Block 385). Multiple recovery attempts were made to recover source and tool, but were unsuccessful. Permission to implement abandonment procedures was given by NRC RIV on 6/28/2013. See report for full details (ADAMS ML13207A409).

CORRECTIVE ACTIONS:

Fishing of the tool was attempted unsuccessfully for over 5 hours. After receiving permission to implement abandonment procedures, 260 feet of red dye cement was poured to form plug from 13043MD feet to 13303MD feet. 181 linear feet of irretrievable heavy drill pipe and other BHA components will serve as the deflection device. A warning plaque was ordered by licensee and will be given to well owner to place into the well file. See ADAMS ML13207A409 for additional information.

RECOMMENDED FOLLOWUP:

Was a reactive inspection conducted?	No	If so, inspection report number :	N/A
Is LER recommended for closure?	Yes		
Is this NMED Item Number recommended to reflect "complete"?	Yes		

LER Evaluator:	Branch Chief or Designee Review:
Name:  Date: <u>1/16/2015</u>	Name:  Date: <u>3/10/15</u>