



PSEG Power, LLC
PSEG Site ESPA
Part 2, Site Safety Analysis Report
Water Surface Elevations at the New
Plant Location Following Failure of the
Cannonsville and Pepacton Dams
FIGURE 2.4.4-3 Rev. 0