



PSEG Power, LLC
 PSEG Site ESPA
 Part 2, Site Safety Analysis Report
 Flow Rates at the New Plant Location
 Following Failure of the Pepacton and
 Cannonsville Dams
 Figure 2.4.4-4 Rev. 0