



PSEG Power, LLC

PSEG Site ESPA

Part 2, Site Safety Analysis Report

---

Initial Water Surface Elevations at Source  
Hispaniola Trench Earthquake Case

FIGURE 2.4.6-22

Rev. 1