



CONTINUED  
NEXT PAGE

PSEG Power, LLC  
PSEG SITE ESPA  
Part 2, Site Safety Analysis Report

Boring Profile - NB-8  
FIGURE 2.5.4.7-2A  
REV 1

