LaSalle Environmental Audit Response to Request for Additional Information

Index #: 038 RAI #: SW-10

Category: Water Resources

Statement of Question:

Provide a water balance/ flow diagram (showing flow rates) for LSCS.

Response:

The requested flow diagram is provided as Attachment 1 to this response.

List of Attachments:

1. Exelon Generation LaSalle County Station Water Flow Schematic, 12/29/2011 (as updated 7/05/2013)

RAI # SW-10

ATTACHMENT 1

