



Indian Point Energy Center
450 Broadway, GSB
P.O. Box 249
Buchanan, N.Y. 10511-0249
Tel.(914) 254-6700

Lawrence Coyle
Site Vice President

NL-15-097

July 30, 2015

U.S. Nuclear Regulatory Commission
ATTN: Document Control Desk
11555 Rockville Pike, OWFN-2F1
Rockville, MD 20852-2738

Subject: Technical Specification 5.6.8, Unit 3 Steam Generator Tube Inspection Report -
Spring 2015 Refueling Outage (3R18)
Indian Point Unit No. 3
Docket No. 50-286
License No. DPR-64

Dear Sir or Madam:

Technical Specification (TS) 5.6.8 (Steam Generator Tube Inspection Report) requires that a report be submitted to the NRC 180 days after initial entry into Mode 4 following completion of a steam generator program inspection in accordance with TS 5.5.8. This letter documents that Entergy Nuclear Operations, Inc. was not required and did not perform any steam generator tube inspections in the spring 2015 refueling outage (3R18), therefore, no formal report is required to be submitted in accordance with TS 5.6.8.

There are no new regulatory commitments are being made by Entergy in this correspondence.

Should you or your staff have any questions regarding this matter, please contact Mr. Robert Walpole, Manager, Regulatory Assurance at (914) 254-6710.

Sincerely,

A handwritten signature in black ink, appearing to be "LC", written over a large, stylized, circular scribble.

LC/cbr

cc: Mr. Daniel H. Dorman, Regional Administrator, NRC Region I
Mr. Douglas Pickett, Senior Project Manager, NRC NRR DORL
NRC Resident Inspectors Office, Indian Point Energy Center
Mrs. Bridget Frymire, New York State Public Service Commission

A001
NRR