REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8107210337: DOC.DATE: 81/07/16 NOTARIZED: NO FACIL:50-269 Ocones Nuclear Station, Unit: 1, Duke Power Co.

DOCKET #:

AUTH NAME

AUTHOR: AFFILIATION

MYERS, D.O. BRYANT, J.C.

Region 2. Atlanta, Office of the Director (81/03/01). Region 2. Atlanta, Office of the Director (81/03/01).

RECIP. NAME

RECIPIENT AFFILIATION

SUBJECT: PNO-IT-81-052: on 810715; during reactor vessel insp, loose parts discovered on vessel bottom. Loose parts identified as 4 of 96 bolts & retainers attaching thermal shield to lower grid flow distributor. Eighty percent of bolts appear loose.

DISTRIBUTION CODE: KOOIS COPIES RECEIVED: LTR J ENCL SIZE: TITLE: Preliminary Notification of Ocurrence or Non-Routine Event

NOTES: AEOD, Ornstein: 1cc.

05000269

<u>.</u>	RECIPIENT	COPIES LITTE ENCL	RECIPIENT: ID CODE/NAME:	COPIES' LTTR: ENCL:
INTERNAL	NRC PDR	1.4	REG FILE	1.
EXTERNAL	DOE EV-141, BARB	1 o'	LPDR NTIS	1: 2 / 2 / 2 / 2 / 2 / 2 / 2 / 2 / 2 / 2

题儿 24 1981

7 S ENCL: #

5/



July 16, 1981

PRELIMINARY NOTIFICATION OF EVENT OR UNUSUAL OCCURRENCE PNO-II-81-52

This preliminary notification constitutes EARLY notice of an event of POSSIBLE safety or public interest significance. The information presented is as initially received without verification or evaluation and is basically all that is known by IE staff as of this date.

FACILITY: Duke Power Company

Oconee Nuclear Station Unit 1

Docket No. 50-269 Seneca, South Carolina

SUBJECT: LOOSE PARTS IDENTIFIED IN REACTOR COOLANT SYSTEM

On July 15 while performing reactor vessel inspections using a remote video camera, as part of the 10 year inservice inspection program, the licensee discovered loose parts in the bottom of the Unit 1 vessel and identified that parts were missing from internal vessel structures. Further inspection revealed that the loose or missing parts consisted of 4 of 96 bolts and retainers attaching the thermal shield to the lower grid flow distributor. Eighty percent of the bolts appear loose. Unit 1 was shut down for this refueling and inspection outage on June 26, and no indications of loose parts monitor alarms were observed prior to Unit shutdown.

The licensee is continuing to investigate this matter. The resident inspectors are following the progress of the licensee.

Media interest is not expected. Neither the licensee nor the NRC plan a news release at this time. The State of South Carolina has been informed.

Region II (Atlanta) received notification of this occurrence by telephone from the resident inspector at 7:30 a.m. on July 16.

Contact: D. O. Myers, RII 242-4190; J. C. Bryant, RII 242-5537

Distribution: Transmittal H. St. Chairman Palladino Commissioner Gilinsky Transmitted: MNBB W. J. Dircks, EDO C. Michelson, AEOD J. J. Fouchard, PA N. M. Haller, MPA H. K. Shapar, ELD Air Rights G. W. Kerr, SP Applicable Resident Site 10:18 Regional Offices Applicable Utility 10:10 USDOT/FHWA - Atlanta

Commissioner Ahearne S. J. Chilk, SECY Commissioner Bradford C. C. Kammerer, CA **ACRS** (For Distribution) P. Bldg. 10:03 IE:TAS (IE:HO Dist.) H. R. Denton, NRR R. H. Vollmer, NRR Landow (6 min/page) T. E. Murley, NRR J. J. Cummings, OIA R. Mattson, NRR D. Eisenhut, NRR MAIL S. H. Hanauer, NRR IE: LAS Willste Document Mgt. Br. (PDR) J. G. Davis, NMSS. S. Ebbin, NSOC R. Minoque. RES

NSAC INPO Facsimile 415/856-6621 Facsimile 404/952-6728 Confirmation 415/855-2998 Confirmation 404/953-5348

PRELIMINARY NOTIFICATION

400/

N NO. II 1 5

DATE:

E: July 16, 1981

PRELIMINARY NOTIFICATION (PN) DISTRIBUTION

INTERNAL RE	EGION II DISTRIBUTION
	Regional Director
	Deputy Regional Director
	Assistant to Director
	Public Affairs Officer
· .	Director, EPOS
***************************************	Director, ETI
	Director, RRPI
	Emergency Preparedness Section Chief
<u> </u>	General File (SSINS No. 6810)
· .	Admin Services Corrdinators: EPOS, RRPI, ETI
,	State Liaison Officer