

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8907050360 DOC.DATE: 89/06/22 NOTARIZED: NO DOCKET #
 FACIL:50-269 Oconee Nuclear Station, Unit 1, Duke Power Co. 05000269
 50-270 Oconee Nuclear Station, Unit 2, Duke Power Co. 05000270
 50-287 Oconee Nuclear Station, Unit 3, Duke Power Co. 05000287

AUTH.NAME AUTHOR AFFILIATION
 TUCKER,H.B. Duke Power Co.
 RECIPIENT NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: Submits response to NRC Bulletin 88-011 re pressurizer surge line thermal stratification.

DISTRIBUTION CODE: IE30D COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 2
 TITLE: Bulletin 88-11 Pressurizer Surge Line Thermal Stratification

NOTES:

	RECIPIENT		COPIES			RECIPIENT		COPIES	
	ID CODE/NAME		LTR	ENCL		ID CODE/NAME		LTR	ENCL
	PD2-3 LA		1	0		PD2-3 PD		1	1
	WIENS,L		1	1					
INTERNAL:	AEOD/DOA		1	1		AEOD/DSP/TPAB		1	1
	AEOD/ROAB		1	1		NRR CHAN,T		1	1
	NRR HOU,S		1	1		NRR KADAMBI,P		1	1
	NRR KUO,P		1	1		NRR/DEST/ADE 8H		1	1
	NRR/DEST/ADS 7E		1	1		NRR/DEST/MEB 9H		1	1
	NRR/DOEA/EAB 11		1	1		NRR/DOEA/GCB 11		1	1
	NRR/DREP/EPB 10		1	1		NRR/PMAS/ILRB12		1	1
	NUDOCS-ABSTRACT		1	1		REG FILE 02		1	1
	RES/DSIR/EIB		1	1		RGN2 FILE 01		1	1
EXTERNAL:	LPDR		1	1		NRC PDR		1	1
	NSIC		1	1					

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTR 24 ENCL 23

AD1 cc

R
I
D
S
/
A
D
D
S

R
I
D
S
/
A
D
D
S

DUKE POWER COMPANY

P.O. BOX 33189

CHARLOTTE, N.C. 28242

HAL B. TUCKER
VICE PRESIDENT
NUCLEAR PRODUCTION

TELEPHONE
(704) 373-4531

June 22, 1989

U. S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

Subject: Oconee Nuclear Station
Docket Nos. 50-269, -270, -287
Pressurizer Surge Line Thermal Stratification
NRC Bulletin 88-11, Dated December 20, 1988


Gentlemen:

The purpose of this letter is to transmit to you the results of our inspection of the Oconee Unit 2 surge line prior to Unit startup expected by the end of June, 1989 as requested by Item 1.a of the subject Bulletin 88-11. Action Item 1.a of the Bulletin requires Duke Power Company to conduct a visual inspection of the pressurizer surge line. This inspection should determine any gross discernible distress or structural damage in the entire pressurizer surge line, including piping, pipe supports, pipe whip restraints, and anchor bolts. The Bulletin requested that any discernible distress and damage observed per Action Item 1.a along with corrective actions taken or plans and schedules for repair shall be reported to NRC before restart of the Unit.

We have completed a visual inspection of the entire surge line during the Unit 2 EOC-10 refueling outage. The inspection which included surge line piping, pipe supports, pipe whip restraints and anchor bolts did not indicate any apparent damage to any of these components.

I declare under penalty of perjury that the statements set forth herein are true and correct to the best of my knowledge.

Very truly yours,



Hal B. Tucker

MAH/9/td

8907050360 890622
PDR ADOCK 05000269
Q PNU

IE30
||

Document Control Desk

June 22, 1989

Page 2

cc: Mr. S. D. Ebnetter
Regional Administrator, Region II
U. S. Nuclear Regulatory Commission
101 Marietta Street, NW, Suite 2900
Atlanta, GA 30323

Mr. L. A. Wiens
Office of Nuclear Reactor Regulatory
U. S. Nuclear Regulatory Commission
Washington, DC 20555

Mr. P. H. Skinner
NRC Resident Inspector
Oconee Nuclear Station