

ACCELERATED DOCUMENT DISTRIBUTION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9304050045 DOC. DATE: 93/03/30 NOTARIZED: NO DOCKET # 05000269
 FACIL: 50-269 Oconee Nuclear Station, Unit 1, Duke Power Co.
 AUTH. NAME AUTHOR AFFILIATION
 HAMPTON, J.W. Duke Power Co.
 RECIP. NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: Submits results of steam generator tube ISI performed during Unit 1 EOC 14 refueling outage. Location & percent of wall-thickness penetration for each indication of degraded tube of SG A & B encl.

DISTRIBUTION CODE: A047D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 67
 TITLE: OR Submittal: Inservice/Testing/Relief from ASME Code

NOTES: *see Reports*

	RECIPIENT		COPIES		RECIPIENT		COPIES	
	ID	CODE/NAME	LTR	ENCL	ID	CODE/NAME	LTR	ENCL
	PD2-3	LA	1	0	PD2-3	PD	1	1
	WIENS,	L	2	2				
INTERNAL:	ACRS		6	6	NRR/DE/EMEB		1	1
	NUDOCS-ABSTRACT		1	1	OC/LFMB		1	0
	OGC/HDS2		1	0	<u>REG FILE</u> 01		1	1
	RES MILLMAN, G		1	1	RES/DSIR/EIB		1	1
EXTERNAL:	EG&G BROWN, B		1	1	EG&G RANSOME, C		1	1
	NRC PDR		1	1	NSIC		1	1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 504-2065) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTR 21 ENCL 18

np-2

Duke Power Company
Oconee Nuclear Generation Department
P.O. Box 1439
Seneca, SC 29679

J.W. HAMPTON
Vice President
(803)885-3499 Office
(704)373-5222 FAX



DUKE POWER

March 30, 1993

U.S. Nuclear Regulatory Commission
Attention Document Control Desk
Washington, DC 20555

Subject: Duke Power Company
Oconee Nuclear Station
Docket No. 50-269
Steam Generator Inservice Inspection
Three (3) Month Report

As required by our Technical Specification 4.17.6(b) we are submitting the results of the Steam Generator Tube Inservice Inspection performed during the Unit 1 EOC 14 refueling outage.

1. The following quantity of tubes were inspected from the inlet or outlet of the Steam Generators:

<u>Steam Generator</u>	<u>Quantity</u>
A	15379
B	14954

2. The following information identifies the location and percent of wall-thickness penetration for each indication of a degraded tube:

<u>Steam Generator</u>	<u>Attachment</u>
A	1
B	2

3. The following information identifies the tubes removed from service by plugging. There were no tubes repaired by sleeving in either Steam Generator:

<u>Steam Generator</u>	<u>Number of Tubes Plugged</u>	<u>Attachment</u>
A	139	3
B	473	4


9304050045 930330
PDR ADOCK 05000269
G PDR

AD47 1/1

U. S. Nuclear Regulatory Commission
Page 2

If there are any questions you may contact M. E. Patrick at (803)
885-3292.

Very truly yours,



J. W. Hampton
Site Vice-President

Attachment

xc: Mr. L. A. Wiens
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, DC 20555

Mr. S. D. Ebnetter
Regional Administrator, Region II
U. S. Nuclear Regulatory Commission

Mr. P. E. Harmon
Senior NRC Resident Inspector
Oconee Nuclear Station

Mr. Heyward G. Shealy
Bureau of Radiological Health
SC Dept. of Health & Environmental Control
2600 Bull St.
Columbia, SC 29201