

ENCLOSURE 1

NOTICE OF VIOLATION

Duke Power Company
Oconee Units 1, 2 and 3

Docket Nos. 50-269, -270, and -287
License Nos. DPR-38, DPR-47 and DPR-55

During the Nuclear Regulatory Commission (NRC) inspection conducted April 22 - May 19, 1990, a violation of NRC requirements was identified. In accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," 10 CFR Part 2, Appendix C (1990), the violation is listed below:

10 CFR 50 Appendix B Criterion III, Design Control, requires measures to be established to assure that design basis requirements are correctly translated into procedures and instructions.

Contrary to the above, between February 1980 to March 1985, requirements were not correctly translated into procedures in that PT/O/A/4980/27A, Routine Test Procedure: Westinghouse CV-7 Relay, required adjusting undervoltage relays for the Auxiliary and Startup Transformer breakers such that during certain grid voltage conditions an inadequate voltage could be applied to safety-related components. This resulted in a condition that would have caused systems designed to prevent or mitigate a serious safety event not being able to perform their intended safety functions.

This is a Severity Level IV Violation (Supplement I).

Pursuant to the provisions of 10 CFR 2.201, Duke Power Company is hereby required to submit a written statement or explanation to the Nuclear Regulatory Commission, ATTN: Document Control Desk, Washington, DC 20555, with a copy to the Regional Administrator, Region II, and a copy to the NRC Resident Inspector within thirty (30) days of the date of the letter transmitting this Notice. This reply should be clearly marked as a "Reply to a Notice of Violation" and should include for each violation: (1) admission or denial of the violation, (2) the reason for the violation if admitted, (3) the corrective steps which have been taken and the results achieved, (4) the corrective steps which will be taken to avoid further violations, and (5) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to

Duke Power Company
Oconee Units 1, 2 and 3

2

Docket Nos. 50-269, -270, and -287
License Nos. DPR-38, DPR-47 and DPR-55

extending the response time. If an adequate reply is not received within the time specified in this Notice, an order may be issued to show cause why the license should not be modified, suspended, or revoked or why such other action as may be proper should not be taken.

FOR THE NUCLEAR REGULATORY COMMISSION

C. W. Hehl / for

Luis A. Reyes, Director
Division of Reactor Projects

Dated at Atlanta, Georgia
this 19th day of June 1990

ENCLOSURE 1

NOTICE OF VIOLATION

Duke Power Company
Oconee Units 1, 2 and 3

Docket Nos. 50-269, -270, and -287
License Nos. DPR-38, DPR-47 and DPR-55

During the Nuclear Regulatory Commission (NRC) inspection conducted April 22 - May 19, 1990, a violation of NRC requirements was identified. In accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," 10 CFR Part 2, Appendix C (1990), the violation is listed below:

10 CFR 50 Appendix B Criterion III, Design Control, requires measures to be established to assure that design basis requirements are correctly translated into procedures and instructions.

Contrary to the above, between February 1980 to March 1985, requirements were not correctly translated into procedures in that PT/O/A/4980/27A, Routine Test Procedure: Westinghouse CV-7 Relay, required adjusting undervoltage relays for the Auxiliary and Startup Transformer breakers such that during certain grid voltage conditions an inadequate voltage could be applied to safety-related components. This resulted in a condition that would have caused systems designed to prevent or mitigate a serious safety event not being able to perform their intended safety functions.

This is a Severity Level IV Violation (Supplement I).

Pursuant to the provisions of 10 CFR 2.201, Duke Power Company is hereby required to submit a written statement or explanation to the Nuclear Regulatory Commission, ATTN: Document Control Desk, Washington, DC 20555, with a copy to the Regional Administrator, Region II, and a copy to the NRC Resident Inspector within thirty (30) days of the date of the letter transmitting this Notice. This reply should be clearly marked as a "Reply to a Notice of Violation" and should include for each violation: (1) admission or denial of the violation, (2) the reason for the violation if admitted, (3) the corrective steps which have been taken and the results achieved, (4) the corrective steps which will be taken to avoid further violations, and (5) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to


Duke Power Company
Oconee Units 1, 2 and 3

2

Docket Nos. 50-269, -270, and -287
License Nos. DPR-38, DPR-47 and DPR-55

extending the response time. If an adequate reply is not received within the time specified in this Notice, an order may be issued to show cause why the license should not be modified, suspended, or revoked or why such other action as may be proper should not be taken.

FOR THE NUCLEAR REGULATORY COMMISSION



Luis A. Reyes, Director
Division of Reactor Projects

Dated at Atlanta, Georgia
this 19 day of June 1990