



Holtec Center, One Holtec Drive, Marlton, NJ 08053

Telephone (856) 797-0900

Fax (856) 797-0909

August 19, 2015

John Goshen, P.E., Project Manager – Licensing Branch  
Division of Spent Fuel Storage and Transportation  
Office of Nuclear Material Safety and Safeguards

ATTN: USNRC Document Control Desk  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555-0001

Docket No. 72-1014  
Certificate of Compliance (CoC) No. 1014

Subject: Issuance of Holtec Information Bulletin (HIB) No. 67 (Rev. 0)

References: [1] HIB 67 Rev. 0 “VCT Restraint Strap Weld Failure”

Dear Mr. Goshen:

The USNRC expressed interest in reviewing Holtec Information Bulletins (HIBs), which are principally used by Holtec to document relevant issues and events pertaining to fuel storage at nuclear plants and to communicate them to the Holtec Users’ Group (HUG) members, the company’s personnel, affected suppliers, and other stakeholders. To that end Holtec hereby submits the attached HIB 67 (Rev. 0) [1].

The HIBs are prepared, internally reviewed and issued expeditiously after an event is determined by the company to be significant to warrant a HIB. Events that merit a HIB may be from suggestions of HUG members, issues identified in the industry at large, or corrective action notifications under 10 CFR Parts 71, 72 or 50 licensees.

The HIB was issued in response to failure of a lifting system component weld.



Holtec Center, One Holtec Drive, Marlton, NJ 08053

Telephone (856) 797-0900

Fax (856) 797-0909

If you have any questions, then please contact me at (856)-797-0900 ext. 3844.

Sincerely,

Royston Ngwayah  
Licensing Engineer  
Holtec International

cc: (letter only, via email)  
Mark Lombard, USNRC  
Michelle Sampson, USNRC

Attachments

Attachment 1: HIB 67 Rev. 0 "VCT Restraint Strap Weld Failure"