

**SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION**

1. LICENSEE/LOCATION INSPECTED:

Blevins Asphalt Construction Co., Inc.  
11837 Lawrence County 1163  
Mt. Vernon, Missouri

REPORT NUMBER(S) 2015-002

2. NRC/REGIONAL OFFICE

Region III  
U. S. Nuclear Regulatory Commission  
2443 Warrenville Road, Suite 210  
Lisle, IL 60532-4352

3. DOCKET NUMBER(S)

030-37419

4. LICENSE NUMBER(S)

24-32645-01

5. DATE(S) OF INSPECTION

8/6/15, with in-office review  
through 8/19/15

**LICENSEE:**

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, to exercise discretion, were satisfied.

\_\_\_\_\_ Non-cited violation(s) were discussed involving the following requirement(s):

- 4. During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited in accordance with NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.  
(Violations and Corrective Actions)

**Statement of Corrective Actions**

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

TITLE	PRINTED NAME	SIGNATURE	DATE
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Robert G. Gattone, Jr.	<i>Robert G. Gattone, Jr.</i>	8/27/15
BRANCH CHIEF	Aaron T. McCraw	<i>[Signature]</i>	8/28/15

**Docket File Information**

**SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION**

1. LICENSEE/LOCATION INSPECTED:  Blevins Asphalt Construction Co., Inc. 11837 Lawrence County 1163 Mt. Vernon, Missouri  REPORT NUMBER(S) 2015-002	2. NRC/REGIONAL OFFICE  Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352
--	---

3. DOCKET NUMBER(S)  030-37419	4. LICENSE NUMBER(S)  24-32645-01	5. DATE(S) OF INSPECTION  8/6/15, with in-office review through 8/19/15
--------------------------------------	---	---

6. INSPECTION PROCEDURES USED  87124	7. INSPECTION FOCUS AREAS  02.01 and 02.07
--	--

**SUPPLEMENTAL INSPECTION INFORMATION**

1. PROGRAM CODE(S)  03121	2. PRIORITY  5	3. LICENSEE CONTACT  David Snyder, RSO	4. TELEPHONE NUMBER  (417) 466-3758
---------------------------------	----------------------	--	---

Main Office Inspection      Next Inspection Date:           No Change          

Field Office Inspection      \_\_\_\_\_

Temporary Job Site Inspection      \_\_\_\_\_

**PROGRAM SCOPE**

This was a post-escalated enforcement inspection; therefore, the next inspection date was not changed as a result of this inspection. The in-office review included receipt and review of information that was unavailable during the onsite inspection, including training records for an authorized user. No temporary job site was inspected because there was no such work conducted within a 2 hours drive from the base facility during the onsite inspection.

**Performance Observations**

The inspector: (1) observed that licensed material was secured as required at the licensee's facility; (2) noted that the licensee was still trying to hire an additional authorized user (AU); (3) observed an AU demonstrate how he had secured licensed material at the base facility and at temporary jobsites; (4) observed an AU demonstrate how he would prevent damage/theft of the gauge at temporary jobsites based on a scenario posed by the inspector; (5) reviewed training records for the AU that participated in the onsite inspection; (6) reviewed records of training that was provided to AUs on or about 6/1/15 that included response to people wanting to see licensed activities being conducted, gauge radiation safety, and the damaged gauge event that resulted in recent escalated enforcement against the licensee (including what was done right, what was done wrong, and the associated NRC reporting requirements in 10 CFR 20.2201, 20.2202, 20.2203, and 30.50).