

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 7908010377 DOC. DATE: 79/07/26 NOTARIZED: NO DOCKET #
 FACIL: 50-269 Oconee Nuclear Station, Unit 1, Duke Power Co. 05000269
 50-270 Oconee Nuclear Station, Unit 2, Duke Power Co. 05000270
 50-287 Oconee Nuclear Station, Unit 3, Duke Power Co. 05000287

AUTH. NAME PARKER, W.O.
 RECIP. NAME DENTON, H.R.
 REID, R.W.
 AUTHOR AFFILIATION Duke Power Co.
 RECIPIENT AFFILIATION Office of Nuclear Reactor Regulation
 Operating Reactors Branch 4

SUBJECT: Submits followup to 790629 ltr re status of certain fire protection mods. Greenfield inside conduit was not sealed as required per upgrading commitment. Error corrected & work completed on 790720. Improper completion shall be prevented.

DISTRIBUTION CODE: A006S COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1
 TITLE: FIRE PROTECTION INFORMATION (AFTER ISSUANCE OF OP. LIC.)

NOTES: M CUNNINGHAM - All AMOS TO FSAR + CHANGES TO TECH SPECS.

	RECIPIENT ID CODE/NAME	COPIES		RECIPIENT ID CODE/NAME	COPIES	
		LTR	ENCL		LTR	ENCL
ACTION:	05 BC ORB 4	4	4			
INTERNAL:	01 REG FILE	1	1	02 NRC PDR	1	1
	09 I&E	2	2	11 TA/EDO	1	1
	12 AUXIL SYS BR	2	2	14 PLANT SYS BR	5	5
	19 WAMBACH	1	1	20 MURANAKA, R	1	1
	21 AD SYS/PROJ	1	1	OELD	1	0
EXTERNAL:	03 LPDR	1	1	04 NSIC	1	1
	22 ACRS	16	16			

AUG 22 1979

TTTAY
 CLD

TOTAL NUMBER OF COPIES REQUIRED: LTR 38 ENCL 0

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

July 26, 1979

TELEPHONE: AREA 704
373-4083

Mr. Harold R. Denton, Director
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Attention: Mr. R. W. Reid, Chief
Operating Reactors Branch No. 4

Re: Oconee Nuclear Station
Docket Nos. 50-269, -270, -287

REGULATORY DOCKET FILE COPY

Dear Sir:

Please refer to my letter of June 29, 1979 regarding the status of certain fire protection modifications at Oconee Nuclear Station.

The commitment to upgrade the Greenfield penetration was inadvertently not fully completed due to a misunderstanding of the requirements. The exterior of the Greenfield conduit was sealed as required. However, the inside of the Greenfield conduit was not sealed with foam by the committed date. This error was corrected by properly sealing the conduit with foam. This work was completed on July 20, 1979.

Efforts have been made to prevent improper completion of required fire protection modifications in the future.

Very truly yours,

William O. Parker, Jr.
William O. Parker, Jr. *By HBSG*

RLG:scs

7908010377

*A006
S 1/0*