

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 7912120294 DOC. DATE: 79/12/05 NOTARIZED: NO  
 FACIL: 50-269 Oconee Nuclear Station, Unit 1, Duke Power Co.  
 50-270 Oconee Nuclear Station, Unit 2, Duke Power Co.  
 50-287 Oconee Nuclear Station, Unit 3, Duke Power Co.  
 AUTH. NAME AUTHOR AFFILIATION  
 PARKER, W.O. Duke Power Co.  
 RECIP. NAME RECIPIENT AFFILIATION  
 DENTON, H.R. Office of Nuclear Reactor Regulation  
 REID, R.W. Operating Reactors Branch 4

DOCKET #  
 05000269  
~~05000270~~  
 05000287

SUBJECT: Notices of failure to retain instruction having both 4160 volt standby buses energized by Lee combustion turbine when one Keowee Hydro unit in svc. Caused by inadequate revision to operating procedure for 100 kV power supply on 791130.

DISTRIBUTION CODE: A002S COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1  
 TITLE: Incident Reports

NOTES: M. CUNNINGHAM - ALL AMENDS TO FSAR & CHANGES TO TECH

*SPECS*

	RECIPIENT ID CODE/NAME	COPIES		RECIPIENT ID CODE/NAME	COPIES	
		LTR	ENCL		LTR	ENCL
ACTION:	05 BC <u>ORB#4</u>	4	4			
INTERNAL:	<u>01 REG FILE</u>	1	1	02 NRC PDR	1	
	09 I&E	2	2	11 MPA	3	
	14 TA/EDO	1	1	15 NOVAK/KNIEL	1	
	16 EEB	1	1	17 AD FOR ENGR	1	
	18 PLANT SYS BR	1	1	19 I&C SYS BR	1	
	20 AD PLANT SYS	1	1	22 REAC SAFT BR	1	
	23 ENGR BR	1	1	24 KREGER	1	
	25 PWR SYS BR	1	1	26 AD/SITE ANAL	1	
	27 OPERA LIC BR	1	1	28 ACIDENT ANLYS	1	
	29 AUX SYS BR	1	1	E JORDAN/IE	1	
	HANAUER, S.	1	1	STS GROUP LEADR	1	
	TMI-H STREET	1	1			
EXTERNAL:	03 LPDR	1	1	04 NSIC	1	
	29 ACRS	16	16			

DEC 14 1979

TOTAL NUMBER OF COPIES REQUIRED: LTR 48 ENCL 0

*AD  
 more 4  
 copy*

# DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.  
VICE PRESIDENT  
STEAM PRODUCTION

December 5, 1979

TELEPHONE: AREA 704  
373-4083

Mr. Harold R. Denton, Director  
Office of Nuclear Reactor Regulation  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

Attention: Mr. Robert W. Reid, Chief  
Operating Reactors Branch No. 4


Re: Oconee Nuclear Station  
Docket Nos. 50-269, -270, -287

Dear Mr. Denton:

On November 30, 1979, the Office of Inspection and Enforcement, Region II, was informed that an inadequacy in the operating procedure for the 100 KV power supply for Oconee Nuclear Station had been discovered. A recent revision to the procedure failed to retain an instruction to have both 4160 volt standby buses energized by a Lee combustion turbine in the event only one Keowee Hydro unit is in service, as required by Technical Specification 3.7.4. As a result, until the situation was corrected on November 30, only one standby bus was energized by a Lee combustion unit during the Keowee Unit 2 maintenance outage.

Pursuant to Technical Specification 3.7.8, a report of the results of the safety evaluation performed as a result of this occurrence was to have been submitted by December 5, 1979. However, the report is still in preparation. It is anticipated that the report will be provided no later than December 10, 1979.

Very truly yours,



William O. Parker, Jr.

SRL/sch

cc: Mr. J. P. O'Reilly, Director



7912120294

A062  
S  
1/D