

**From:** [Vega, Frankie](#)  
**To:** [al.maysam@duke-energy.com](mailto:al.maysam@duke-energy.com)  
**Cc:** [Shams, Mohamed](#); [DiFrancesco, Nicholas](#); [Jackson, Diane](#)  
**Subject:** Editorial error - Robinson Rec. 2.1 Seismic Staff Assessment  
**Date:** Friday, November 06, 2015 8:03:00 AM  
**Attachments:** [image001.png](#)

---

Mr. Maysam;

The NRC staff acknowledges that an editorial error was encountered in the Seismic Staff Assessment (SA) for Robinson issued on October 19, 2015 (ML15280A199). This editorial error can be found in SA Section 3.1 "Plant Seismic Design-Basis" in the following sentence:

*The licensee specified that the SSE control point is located at the top of ground surface at a mean sea level elevation of 226 ft. (68.9 m) **approximately 85 ft. (26 m) below plant grade elevation.***

The second part of the sentence, marked in red, incorrectly describes the SSE control point elevation and thus, should not have been included as part of this description. The staff has noted this error and does not see a need to issue a formal correction letter since the overall SA conclusion remains intact and it will not impact other activities associated with NTTF Rec 2.1 "Seismic".

If you have questions feel free to contact me.

Thanks



**Frankie G. Vega, P.E.**  
**Project Manager**  
NRR/JLD/JHMB  
301-415-1617  
Location: O-13H12