

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:

JanX Integrity Group
8550 East Michigan Avenue
Parma, MI 49269
Location Inspected: Job Site in Six Lakes, Michigan

REPORT NUMBER(S) 2015-004

2. NRC/REGIONAL OFFICE

Region III
U. S. Nuclear Regulatory Commission
2443 Warrenville Road, Suite 210
Lisle, IL 60532-4352

3. DOCKET NUMBER(S)

030-11772

4. LICENSE NUMBER(S)

21-16560-01

5. DATE(S) OF INSPECTION

November 19, 2015

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:



- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, to exercise discretion, were satisfied.

_____ Non-cited violation(s) were discussed involving the following requirement(s):

- 4. During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited in accordance with NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.
(Violations and Corrective Actions)

Statement of Corrective Actions

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

TITLE	PRINTED NAME	SIGNATURE	DATE
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Ryan Craffey		11/24/15
BRANCH CHIEF	Aaron McCraw		11/25/15

Docket File Information
SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: JanX Integrity Group 8550 East Michigan Avenue Parma, MI 49269 Location Inspected: Job Site in Six Lakes, Michigan REPORT NUMBER(S) 2015-004	2. NRC/REGIONAL OFFICE Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352
---	---

3. DOCKET NUMBER(S) 030-11772	4. LICENSE NUMBER(S) 21-16560-01	5. DATE(S) OF INSPECTION November 19, 2015
--------------------------------------	---	---

6. INSPECTION PROCEDURES USED 87121	7. INSPECTION FOCUS AREAS All
--	--------------------------------------

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S) 03320	2. PRIORITY 1	3. LICENSEE CONTACT William Reeve - RSO	4. TELEPHONE NUMBER (517) 531-8210
---------------------------------	----------------------	--	---

Main Office Inspection Next Inspection Date: No change

Field Office Inspection _____

Temporary Job Site Inspection Cutler Road west of M-66, Six Lakes, MI 48886

PROGRAM SCOPE

This was a temporary job site inspection of a large non-destructive testing company authorized to use radioactive material for industrial radiography at numerous field stations and at temporary job sites throughout NRC jurisdiction. At the time of the inspection, the licensee scheduled work for its Michigan operations from a field station in Mount Pleasant and maintained radiographic equipment at this station, as well as at its main office in Parma, Michigan.

PERFORMANCE OBSERVATIONS

The inspector observed the conduct of radiographic operations at a DTE laydown yard approximately half a mile west of M-66 on Cutler Road in Six Lakes, Michigan. The inspector noted the satisfactory set-up and use of restricted area barriers and during these operations, as confirmed by independent surveys. Through subsequent discussions of such topics as barrier calculations, equipment checks and survey instrument and dosimetry use, the inspector found that the radiographer and his assistant were knowledgeable of radiation protection principles and licensee procedures, and their dosimetry and survey instruments were calibrated and operable.

The inspector reviewed a selection of available safety-related records, including utilization logs, shipping papers, leak test results for source and camera, and the licensee's most recent revision to its operating and emergency procedures.

No violations of NRC safety requirements were identified as a result of this inspection. The inspector conducted a telephonic exit meeting with the licensee's RSO on November 19, 2015.