



U.S. Nuclear Regulatory Commission  
ATTN: Document Control Desk  
Washington, DC 20555-0001

DCS-NRC-000411  
16 December 2015

Subject: Docket Number 070-03098  
CB&I AREVA MOX Services  
Mixed Oxide Fuel Fabrication Facility  
Part 21 60-Day Interim Report Notification: Byers Precision Fabricators

This letter provides interim information concerning an evaluation being performed by CB&I AREVA MOX Services, LLC (MOX Services) regarding a nonconformance identified at the Mixed Oxide Fuel Fabrication Facility. The nonconformance being evaluated pertains to vendor application of standard welding procedure specifications during fabrication of six gloveboxes.

Evaluation of reportability in accordance with §21.21(a)(1) is not able to be completed within the 60-day evaluation period as additional time is required to collect and evaluate the necessary information.

The information required for a 60-Day Interim Report Notification per §21.21(a)(2) is provided in the Enclosure. It is currently expected that the evaluation of this condition will be completed by 28 April 2016.

If you have any questions, please feel free to contact me at (803) 442-6485 or our Licensing and Nuclear Safety Manager, Dealis Gwyn, at (803) 819-2780.

Sincerely,

A handwritten signature in black ink that reads 'David Del Vecchio'. The signature is written in a cursive style and extends across the width of the page.

David Del Vecchio  
President and Project Manager

Document Control Desk  
U.S. Nuclear Regulatory Commission  
DCS-NRC-000411  
16 December 2015  
Page 2 of 2

Enclosure:

60-Day Interim Report Notification Information per §21.21(a)(2)

cc :

Kevin Buchanan, NNSA/SRS  
Scott Cannon, NNSA/SRS  
Mark Gober, MOX Services  
Carol Elliott, NNSA/SRS  
William Gloersen, USNRC/RII  
Dealis Gwyn, MOX Services  
Chip Hicks, MOX Services  
Chad Huffman, USNRC/SRS  
Dennis Ivey, MOX Services  
Kevin Morrissey, USNRC/HQ  
Regional Administrator, USNRC/RII  
Gilles Rousseau, MOX Services  
Deborah Seymour, USNRC/RII  
Donald Silverman, ML&B  
David Tiktinsky, USNRC/HQ  
Paul Whittingham, MOX Services  
Bryan Wilkes, MOX Services  
Lauren Wylie, MOX Services  
Doug Yates, MOX Services  
MOX Project Management Office Document Control Administrator (moxpmodca@srs.gov)  
EDMS: Corresp\Outgoing\NRC\2015 NRC

**Enclosure**

**60-Day Interim Report Notification Information per §21.21(a)(2)**

**60-Day Interim Report Notification Information per §21.21(a)(2)**

- (i) Name and address of the individual or individuals informing the Commission.

David Del Vecchio  
President and Project Manager  
CB&I AREVA MOX Services  
Savannah River Site  
P.O. Box 7097  
Aiken, SC 29804-7097

- (ii) Identification of the facility, the activity, or the basic component supplied for such facility which fails to comply or contains a defect.

The Mixed Oxide Fuel Fabrication Facility is evaluating a nonconforming condition associated with vendor non-adherence to standard welding procedure specifications during fabrication of six gloveboxes. No basic components have been determined to contain a defect.

- (iii) Identification of the firm constructing the facility or supplying the basic component which fails to comply or contains a defect.

No basic components have been determined to contain a defect. This is an interim report. The six gloveboxes were supplied to MOX Services as a basic component by Byers Precision Fabricators, Inc. 675 Dana Road, Hendersonville, NC 28792.

- (iv) Nature of the defect or failure to comply and the safety hazard which is created or could be created by such defect or failure to comply.

No basic components have been determined to contain a defect. This is an interim report. MOX Services is evaluating vendor non-adherence to standard welding procedure specifications during fabrication of six gloveboxes.

- (v) The date on which the information of such defect or failure to comply was obtained.

Information related to the nonconforming welding procedures was provided to MOX Services by Byers Precision Fabricators on October 29, 2015.

- (vi) In the case of a basic component which contains a defect or fails to comply, the number and location of these components in use at, supplied for, being supplied for, or may be supplied for, manufactured, or being manufactured for one or more facilities or activities subject to the regulations in this part.

MOX Services does not possess information as to whether other facilities have been supplied a similar basic component by Byers Precision Fabricators.

- (vii) The corrective action, which has been, is being, or will be taken; the name of the individual or organization responsible for the action; and the length of time that has been or will be taken to complete the action.

No basic components have been determined to contain a defect. This is an interim report. MOX Services engineering anticipates completion of our Part 21 reportability evaluation by 28 April 2016.

- (viii) Any advice related to the defect or failure to comply about the facility, activity, or basic component that has been, is being, or will be given to purchasers or licensees.

None at this time.

- (ix) In the case of an early site permit, the entities to whom an early site permit was transferred.

Not applicable.