

**NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)**

CONTROL NO: 9301

FILE: INCIDENT REPORT FILE

5-4

FROM: Duke Power Co. Charlotte, N.C. William O. Parker		DATE OF DOC 8-27-75	DATE REC'D 9-2-75	LTR	TWX	RPT XX	OTHER
TO: NRC		ORIG None	CC	OTHER	SENT AEC PDR XXX		SENT LOCAL PDR XXX
CLASS	UNCLASS XXX	PROP INFO	INPUT	NO CYS REC'D 1	DOCKET NO: 50-270		

DESCRIPTION:
Letter trans the following.....

PLANT NAME: Oconee 2

ENCLOSURES:
Unusual Event # 75-11, on 7-28-75, Concerning Inadvertent removal of high energy line break door.....

(1 Copy Enclosure Received)

FOR ACTION/INFORMATION

SAB 9-3-75

BUTLER (L) W/ Copies	SCHWENCER (L) W/ Copies	ZIEMANN (L) W/ Copies	REGAN (E) W/ Copies
CLARK (L) W/ Copies	STOLZ (L) W/ Copies	DICKER (E) W/ Copies	LEAR (L) W/ Copies
PARR (L) W/ Copies	VASSALLO (L) W/ Copies	KNIGHTON (E) W/ Copies	SPELS W/ Copies
KNIEL (L) W/ Copies	PURPLE (L) W/ Copies	YOUNGBLOOD (E) W/ Copies	

**DO NOT REMOVE
ACKNOWLEDGED**

INTERNAL DISTRIBUTION

<u>REG FILE</u> NRC PDR OGC, ROOM P-506A GOSSICK/STAFF CASE GIAMBUSSO BOYD MOORE (L) DEYOUNG (L) SKOVHOLT (L) GOLLER (L) (Ltr) P. COLLINS DENISE REG OPR FILE & REGION (2) MIPC/PE (3) STEELE	TECH REVIEW SCHROEDER MACCARY KNIGHT PAWLICKI SHAO **STELLO **HOUSTON **NOVAK ROSS IPPOLITO TEDESCO J. COLLINS LAINAS BENAROYA VOLLMER	DENTON **GRIMES GAMMILL KASTNER BALLARD SPANGLER ENVIRO MULLER DICKER KNIGHTON YOUNGBLOOD REGAN PROJECT LDR HARLESS	LIC ASST R. DIGGS (L) H. GEARIN (L) E. GOULBOURNE (L) P. KREUTZER (E) J. LEE (L) M. RUSHBROOK (L) S. REED (E) M. SERVICE (L) S. SHEPPARD (L) M. SLATER (E) H. SMITH (L) S. TEETS (L) G. WILLIAMS (E) V. WILSON (L) R. INGRAM (L) M. DUNCAN (E)	A/T IND. BRAITMAN SALTZMAN MELTZ PLANS MCDONALD CHAPMAN DUBE (Ltr) E. COUPE PETERSON HARTFIELD (2) KLECKER EISENHUT WIGGINTON F. WILLIAMS HANAUER
---	---	--	--	--

EXTERNAL DISTRIBUTION

1 - LOCAL PDR <u>Walhalla, S.C.</u>	1 - NATIONAL LABS	1 - PDR-SAN/LA/NY
1 - TIC (ABERNATHY) (1)(2)(10)	1 - W. PENNINGTON, Rm E-201 GT	1 - BROOKHAVEN NAT LAB
1 - NSIC (BUCHANAN)	1 - CONSULTANTS	1 - G. ULRIKSON, ORNL
1 - ASLB	NEWMARK/BLUME/AGBABIAN	1 - AGMED (RUTH GUSSMAN) Rm B-127 GT
1 - Newton Anderson		1 - J. D. RUNKLES, Rm E-201 GT

5 - AERS sent to L.A. S. Sheppard
** SEND ONLY TEN DAY REPORTS

DUKE POWER COMPANY
POWER BUILDING
422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242


WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

TELEPHONE: AREA 704
373-4083

August 27, 1975

Regulatory

File Cy.




Mr. Norman C. Moseley, Director
U. S. Nuclear Regulatory Commission
Suite 818
230 Peachtree Street, Northwest
Atlanta, Georgia 30303

Re: Oconee Unit 2
Docket No. 50-270

Dear Mr. Moseley:

Pursuant to Sections 6.2 and 6.6.2 of the Oconee Nuclear Station
Technical Specifications, please find attached Unusual Event Report
UE-270/75-11.


Very truly yours,



William O. Parker, Jr.

MST:vr
Attachment

cc: Mr. Roger S. Boyd



9301

DUKE POWER COMPANY
OCONEE UNIT 2

Report No.: UE-270/75-11

Report Date: August 27, 1975

Event Date: July 28, 1975

Facility: Oconee Unit 2, Seneca, South Carolina

Identification of Event: Inadvertent removal of high energy line break door

Conditions Prior to Event: Unit 1, cold shutdown
Unit 2, power operation

Description of Event:

On July 28, 1975, a modification to Oconee Unit 1 was performed to replace the temporary "high energy line break doors" with a permanent installation. The prerequisite condition for performing this modification was that the appropriate unit be in a cold shutdown condition prior to replacing the doors. In the performance of the procedure, personnel unfamiliar with the Auxiliary Building layout removed the door to the Unit 2 rather than Unit 1 cable room while Unit 2 was at power operation. This situation was immediately reported to the Shift Supervisor and the door replaced within three hours.

Designation of Apparent Cause of Event:

The procedure used for this modification listed the doors which were to be replaced and specified that the applicable unit had to be in a cold shutdown condition. It did not, however, specify which doors were applicable to each unit. Personnel not familiar with the Auxiliary Building layout confused the Unit 2 door with the Unit 1 door.

Analysis of Event:

The high energy line break doors are provided to protect the cable room from overpressurization and missile damage which might result during a postulated main steam or main feedwater break. The door was removed for only a short period of time, thus there was a very remote possibility of a line break at the same time. It is concluded that the health and safety of the public was not affected.

Corrective Action:

The high energy line break door was replaced immediately following the discovery of this incident. In order to prevent future recurrence, the modification procedure has been revised to show those doors which are to be replaced during the time each unit is shut down.

50-270/75-11

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

TELEPHONE: AREA 704
373-4083

August 27, 1975

Mr. Norman C. Moseley, Director
U. S. Nuclear Regulatory Commission
Suite 818
230 Peachtree Street, Northwest
Atlanta, Georgia 30303



Re: Oconee Unit 2
Docket No. 50-270

Dear Mr. Moseley:

Pursuant to Sections 6.2 and 6.6.2 of the Oconee Nuclear Station
Technical Specifications, please find attached Unusual Event Report
UE-270/75-11.

Very truly yours,

William O. Parker, Jr.
William O. Parker, Jr.

MST:vr
Attachment

cc: Mr. Roger S. Boyd



DUKE POWER COMPANY
OCONEE UNIT 2

Report No.: UE-270/75-11

Report Date: August 27, 1975

Event Date: July 28, 1975

Facility: Oconee Unit 2, Seneca, South Carolina

Identification of Event: Inadvertent removal of high energy line break door

Conditions Prior to Event: Unit 1, cold shutdown
Unit 2, power operation

Description of Event:

On July 28, 1975, a modification to Oconee Unit 1 was performed to replace the temporary "high energy line break doors" with a permanent installation. The prerequisite condition for performing this modification was that the appropriate unit be in a cold shutdown condition prior to replacing the doors. In the performance of the procedure, personnel unfamiliar with the Auxiliary Building layout removed the door to the Unit 2 rather than Unit 1 cable room while Unit 2 was at power operation. This situation was immediately reported to the Shift Supervisor and the door replaced within three hours.

Designation of Apparent Cause of Event:

The procedure used for this modification listed the doors which were to be replaced and specified that the applicable unit had to be in a cold shutdown condition. It did not, however, specify which doors were applicable to each unit. Personnel not familiar with the Auxiliary Building layout confused the Unit 2 door with the Unit 1 door.

Analysis of Event:

The high energy line break doors are provided to protect the cable room from overpressurization and missile damage which might result during a postulated main steam or main feedwater break. The door was removed for only a short period of time, thus there was a very remote possibility of a line break at the same time. It is concluded that the health and safety of the public was not affected.

Corrective Action:

The high energy line break door was replaced immediately following the discovery of this incident. In order to prevent future recurrence, the modification procedure has been revised to show those doors which are to be replaced during the time each unit is shut down.