

NRC FORM 691M PART 1 (07-2012) 10 CFR 2.201		U.S. NUCLEAR REGULATORY COMMISSION	
SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION			
1. LICENSEE/LOCATION INSPECTED: Mercy, Advanced Heart Care 1414 Stewart Road Monroe, Michigan 48161 REPORT NUMBER(S) 2016-001		2. NRC/REGIONAL OFFICE Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352	
3. DOCKET NUMBER(S) 030-35041	4. LICENSE NUMBER(S) 21-32186-01	5. DATE(S) OF INSPECTION January 22, 2015 ⁶ ²⁰¹⁶	

LICENSEE:
 The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

1. Based on the inspection findings, no violations were identified.

2. Previous violation(s) closed.

3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, to exercise discretion, were satisfied.

_____ Non-cited violation(s) were discussed involving the following requirement(s):

4. During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited in accordance with NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.
 (Violations and Corrective Actions)

Statement of Corrective Actions

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

TITLE	PRINTED NAME	SIGNATURE	DATE
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Geoffrey M. Warren / Edward Harvey	<i>Geoffrey M. Warren</i>	1/22/16
BRANCH CHIEF	Aaron T. McCraw	<i>Aaron T. McCraw</i>	2/1/16

Docket File Information

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: Mercy, Advanced Heart Care 1414 Stewart Road Monroe, MI 48161 REPORT NUMBER(S) 2016-001	2. NRC/REGIONAL OFFICE Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352
---	---

3. DOCKET NUMBER(S) 030-35041	4. LICENSE NUMBER(S) 21-32186-01	5. DATE(S) OF INSPECTION January 22, 2016
--------------------------------------	---	--

6. INSPECTION PROCEDURES USED 87130	7. INSPECTION FOCUS AREAS 3.01-3.08
--	--

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S) 02121	2. PRIORITY 5	3. LICENSEE CONTACT Prem C. Ghai, MD, RSO	4. TELEPHONE NUMBER (734) 242-8880
---------------------------------	----------------------	--	---

Main Office Inspection Next Inspection Date: January 22, 2021

Field Office Inspection _____

Temporary Job Site Inspection _____

PROGRAM SCOPE

This was a routine inspection of a private cardiovascular clinic authorized to use licensed material permitted by 10 CFR 35.200. The licensee was not performing any licensed activities at the time of the inspection due to a change of ownership that resulted in the loss of their nuclear medicine technologist. The last administration under this license occurred on November 15, 2015. The licensee performed approximately 5-10 diagnostic procedures per week prior to the last administration.

No performance observations were conducted as a result of the temporary cessation of licensed activities. Review of records including dose calibrator constancy checks, package receipt, daily surveys, waste disposal, and dosimetry indicated that the program was operating in accordance with Federal regulations. The inspectors verified that all sources listed in the licensee's inventory were secured within the hot lab. Independent measurements were performed to verify that 10 CFR Part 20 radiation limits were not exceeded.

The licensee has submitted a request to amend their license to reflect the change of ownership effective January 13, 2016. At the time of the inspection, the licensee was evaluating options to continue licensed activities, including utilizing a mobile service or hiring new staff within the clinic.

No violations were identified during this inspection.