

UNITED STATES NUCLEAR REGULATORY COMMISSION REGION II 101 MARIETTA ST., N.W., SUITE 3100 ATLANTA, GEORGIA 30303

In Reply Refer To: RII:JPO 50-369, 50-370 50-269, 50-270 50-297, 50-413 50-414 APR 2 9 1980

REGULATORY DOCUMENTILE COPY

8005190 556

Duke Power Company Attn: W. O. Parker, Jr. Vice President, Steam Production P. O. Box 2178 Charlotte, NC 28242

Gentlemen:

The enclosed Circular No. 80-10, is forwarded to you for information. If there are any questions related to your understanding of the suggested actions, please contact this office.

Sincerely,

James P. O'Reilly Director

Enclosures:

14.6.4.4.4

.

- 1. IE Circular No. 80-10
- 2. List of Recently Issued IE Circulars

cc w/encl: J. W. Hampton, Station Manager Post Office Box 392 Clover, South Carolina 29710

D. G. Beam, Project Manager Post Office Box 223 Clover, South Carolina 29710

M. D. McIntosh, Plant Manager Post Office Box 488 Cornelius, North Carolina 28031

J. C. Rogers, Project Manager Post Office Box 33189 Charlotte, North Carolina 28242

J. E. Smith, Station Manager Post Office Box 1175 Seneca, South Carolina 29678

ina y ini yang ini Bangan na ang propinsi Dagan na ang propinsi

· · · ·

a la er er

ander en der soner eine eine eine einen eine einen eine einen eine einen eine einen einen einen einen einen eine Aus eine einen eine einen ei

SSINS No.: 6830 Accession No.: 8002280665

UNITED STATES NUCLEAR REGULATORY COMMISSION OFFICE OF INSPECTION AND ENFORCEMENT WASHINGTON, D.C. 20555

April 29, 1980

IE Circular No. 80-10

FAILURE TO MAINTAIN ENVIRONMENTAL QUALIFICATION OF EQUIPMENT

Description of Circumstances:

Carolina Power and Light recently reported that the wrong class of insulating material had been used at their H. B. Robinson Nuclear Plant when the motor leads of a containment fan cooler were reconnected. The motor leads had been disconnected during the refueling outage to supply power to welding equipment. When the motor leads were reconnected, the wrong class of insulating material degraded the environmental qualification of the containment fan cooler motor. A similar event, reported by Duquesne Light Company, occurred when a containment fan cooler motor was not installed with the proper cable insulation.

The NRC has previously issued IE Circular 78-08 and IE Bulletins 79-01 and 79-01B concerning environmental qualification of Class IE equipment. These Bulletins primarily address the environmental qualification of equipment as purchased and installed; however, the above events emphasize the importance of properly installing and maintaining environmentally qualified equipment.

Recommended Action for Licensee Consideration:

All holders of operating licenses or construction permits should recognize the potential for degradation of environmentally qualified equipment due to improper maintenance or improper use. It is recommended that licensees review current maintenance procedures and administrative policies to ensure the following:

- 1. Adequate administrative controls exist to ensure that equipment which is environmentally qualified is identified prior to maintenance.
- 2. Maintenance procedures provide necessary instructions and precautions to ensure that the environmental qualification of equipment is not degraded when maintenance is completed.
- 3. Maintenance personnel are adequately trained on environmental qualification requirements and the potential for equipment degradation from improper maintenance.

No written response to this Circular is required. If you require additional information regarding this matter, contact the Director of the appropriate NRC Regional Office.

IE Circular No. 80-10 April 29, 1980

Enclosure

RECENTLY ISSUED IE CIRCULARS

		· · · · · · · · · · · · · · · · · · ·	
Circular No.	Subject	Date of Issue	Issued to
80-10	Failure to Maintain Environ- mental Qualification of Equipment	4/29/80	All holders of a power reactor OL or CP
80-09	Problems with Plant Internal Communications Systems	4/28/80	All holders of a power reactor OL or CP
80-08	BWR Technical Specification Inconsistency - RPS Response Time	4/18/80	All General Electric BWR's holding a power reactor OL
80-07	Problems with HPCI Turbine Oil System	4/3/80	All holders of a power reactor OL or CP
80-06	Control and Accountability Systems for Implant Therapy Sources	4/14/80	Medical licensees in Categories G and Gl
80-05	Emergency Diesel-Generator Lubricating Oil Addition and Onsite Supply	4/1/80	All holders of a power reactor OL or CP
80-04	Securing of Threaded Locking Devices on Safety-Related Equipment	3/14/80	All holders of a power reactor OL or CP
80-03	Protection from Toxic Gas Hazards	3/6/80	All holders of a power reactor OL
80-02	Nuclear Power Plant Staff Work Hours	2/1/80	All holders of Reactor OLs, including research and test reactors, and CPs
80-01	Service Advice for GE Induction Disc Relays	1/17/80	All licensees of nuclear power reactor operating facilities
			and holders of nuclear power reactor CPs
		· · · · · · · · · · · · · · · · · · ·	The second se