ACCESSION NBR:8102020390 DOC.DATE: 81/01/27 NOTARIZED: NO FACIL:50+287 Oconee Nuclear Station, Unit 3, Duke Power Co.

DOCKET # 05000287

AUTH.NAME

AUTHOR AFFILIATION

PARKER, W.O. RECIP.NAME

Duke Power Co.

O'REILLY, J.P.

RECIPIENT AFFILIATION
Region 2, Atlanta, Office of the Director

SUBJECT: RO80-16:corrective action section of 801223 submittal should be changed. Detector cleaned & verified operable before returning to svc.

DISTRIBUTION CODE: A002S COPIES RECEIVED:LTR ___ ENCL __ SIZE:__________
TITLE: Incident Reports

NOTES:M Cunningham:all amends to FSAR & changes to Tech Specs. AEOD,Ornstein:1cc

05000287

	RECIPIENT	COPIES		RECIPIENT	COPIES	
	ID CODE/NAME	LTTR	ENCL	ID CODE/NAME	LTTR	ENCL
ACTION:	REID,R. 04	3	3			
INTERNAL:	A/D COMP&STRU06	1	1	A/D ENV TECH 07	1	1
	A/D MATL & QUOB	1	1	A/D OP REACTOOS	1	1
	A/D PLANT SYS10	1	1	A/D RAD PROT 11	1	1
	A/D SFTY ASSE12	1	1	A/D TECHNOLOG13	1	1
	ACC EVAL BR 14	1	1	AEOD	3	3
	ASLBP/J.HARD	1	1	AUX SYS BR 15	1	1
	CHEM ENG BR 16	1	1	CONTESYS BR 17	1	1
	CORE PERF BR 18	1	1	D/DIR, HUM FAC19	1	1
	DIR, DIV OF LIC	1	1	DIR, ENGINEERI20	1	1
	DIR, HUM FAC \$21	1	1	DIR, SYS INTEG22	1	1
	EFF TR SYS BR23	1	1	EQUIP QUAL BR25	1	1
	GEOSCIENCES 26	1	1	I&C SYS BR 29	1	1
	I&E 05	2	2	JORDAN, E./IE	1,	1
	LIC GUID BR 30	1	1	LIC QUAL BR 31	1	1
	MATL ENG BR 32	1	1	MECH ENG BR 33	1	1
•	MPA	3	3	NRC PDR 02	1	1.
	OP EX EVAL BR34	3	3	OR ASSESS BR 35	1	1
	POWER SYS BR 36	1	1	RAD ASSESS BR39	1	1
	REACT SYS BR 40	1	1	FEG FILE 01	1	1
	REL & RISK A 41	1	1	SFTY PROG EVA42	1	1 -
	STRUCT ENG BR44	1	1	SYS INTERAC 845	1	1
EXTERNAL:	ACRS 46	16	16	LPDR 03	1	· 1.
	NSIC 05	1	1	TERA: DOUG MAY	1	1

FFB 0 3 1981

72 72

71 ENCL

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR. VICE PRESIDENT STEAM PRODUCTION

TELEPHONE: AREA 704 373-4083

January 27, 1981

Mr. James P. O'Reilly, Director U. S. Nuclear Regulatory Commission Region II 101 Marietta Street, Suite 3100 Atlanta, Georgia 30303

Oconee Nuclear Station Docket No. 50-287

Dear Mr. O'Reilly:

Reportable Occurrence Report RO-287/80-16, "Fire Detector String B-2 Removed From Service," was submitted to your office on December 23, 1980. The Corrective Action section should be changed to read:

Corrective Action:

The detector was cleaned and verified operable before returning to service. All accessible fire detectors in the areas of roll up doors or other areas susceptible to dusty conditions will be cleaned on an increased frequency to remove dust buildup.

My letter of January 13, 1981 incorrectly identified this incident as Reportable Occurrence Report RO-287/80-34.

Very truly yours,

William O. Parker, Jr. by WAH

JLJ:pw

cc: Director Office of Management & Program Analysis U. S. Nuclear Regulatory Commission Washington, D. C. 20555

Mr. Bill Lavallee Nuclear Safety Analysis Center P. O. Box 10412

Palo Alto, California 94303