

A002

REGULATORY INFORMATION DISTRIBUTION SYSTEM

DOCKET NBR: 50-269 OCONEE 1
RECIPIENT: O'REILLY, J.P.
ORIGINATOR: PARKER, W.O.
COMPANY NAME: DUKE PWR
SUBJECT:
DOC DATE: 781127
ACCESSION NBR: 7812010244
COPIES RECEIVED:
LTR 1 ENCL 1
SIZE: 1+2

LER#78-025/03L-0 on 781026: During annual RPS recalibr the RPS trip setpoint was found to be less conservative than allowed by Tech Spec limits. Caused by effect of temp/ humidity changes resulting from May 1978 pressure switch failure.

DISTRIBUTION CODE: A002
DISTRIBUTION TITLE:
INCIDENT REPORTS
NOTARIZED

NAME	ENCL?	FOR ACTION
BR CHTPP	W/4 ENCL	• ORB#4 BC
REG FILE	W/ENCL	
NRC PDR	W/ENCL	
I & E	W/2 ENCL	
MIPC	W/3 ENCL	
I & C SYSTEMS BR	W/ENCL	
NOVAK/CHECK	W/ENCL	
EEB	W/ENCL	
AD FOR ENG	W/ENCL	
PLANT SYSTEMS BR	W/ENCL	
HANAUER	W/ENCL	
AD FOR PLANT SYSTEMS	W/ENCL	
AD FOR SYS & PROJ	W/ENCL	
REACTOR SAFETY BR	W/ENCL	
ENGINEERING BR	W/ENCL	
KREGER/J. COLLINS	W/ENCL	
POWER SYS BR	W/ENCL	
E. Jordan	W/ENCL	
LPDR	W/ENCL	
NSIC	W/ENCL	
ACRS	W/16 ENCL	

DEC 4 1978

TOTAL NUMBER OF COPIES REQUIRED:
LTR 42
ENCL 42

NOTES: M CUNNINGHAM - ALL AMDTS TO FSAR & CHANGES TO TECH SPECS.

A104
ccp

DUKE POWER COMPANY
POWER BUILDING
422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

November 27, 1978

TELEPHONE: AREA 704
373-4083


Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

RE: Oconee Unit 1
Docket No. 50-269

Dear Mr. O'Reilly:

Pursuant to Sections 6.2 and 6.6.2 of the Oconee Nuclear Station Technical Specifications, please find attached Reportable Occurrence Report RO-269/78-25.

Very truly yours,


William O. Parker, Jr.

KRW:scs

Attachment

cc: Director, Office of Management Information
and Program Control

REGULATORY DOCKET FILE COPY

781201 0244

A002
5/1