

REGULATOR INFORMATION DISTRIBUTION TEM (RIDS)

ACCESSION NBR: 7906140353 DOC. DATE: 79/05/07 NOTARIZED: NO
 FACIL: 50-269 Oconee Nuclear Station, Unit 1, Duke Power Co.
 AUTH. NAME: VITO, D. J.
 RECIP. NAME: VITO, D. J.
 AUTHOR AFFILIATION: Duke Power Co.
 RECIPIENT AFFILIATION: Region 3, Chicago, Office of the Director

DOCKET #
05000269

SUBJECT: RO 269/79-13 on 790507: quadrant power tilt was beyond error-adjusted steady-state limit. Caused by power increases after Emergency Feedwater pump flow stability test. Power reduced to evaluate tilt.

DISTRIBUTION CODE: A002S COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1
 TITLE: INCIDENT REPORTS

NOTES: M. CUNNINGHAM - ALL AMENDS TO FSAR & CHANGES TO TECH SPECS.

ACTION:	RECIPIENT	COPIES		RECIPIENT	COPIES	
	ID CODE/NAME	LTR	ENCL	ID CODE/NAME	LTR	ENCL
	05 BC ORB#4	4	4			
INTERNAL:	01 REG FILE	1	1	02 NRC PDR	1	1
	09 IBE	2	2	11 MPA	3	3
	14 TA/EDO	1	1	15 NOVAK/KNIEL	1	1
	16 EEB	1	1	17 AD FOR ENGR	1	1
	18 PLANT SYS BR	1	1	19 I&C SYS BR	1	1
	20 AD PLANT SYS	1	1	21 AD SYS/PROJ	1	1
	22 REAC SAFT BR	1	1	23 ENGR BR	1	1
	24 KREGER	1	1	25 PWR SYS BR	1	1
	26 AD/SITE ANAL	1	1	27 OPERA LIC BR	1	1
	28 ACCIDENT ANALYS	1	1	29 AUX SYS BR	1	1
	E JORDAN/IE	1	1	HANAUER, S.	1	1
	TMI DOC CENTER	1	1			
EXTERNAL:	03 LPDR	1	1	04 NSIC	1	1
	29 ACRS	16	16			

copy
cep

TO: Frank Tape
OCONEE NRC/OIE PRINCIPAL INSPECTOR

- E. P. O'REILLY
- M. UPRIGHT
- D. CHENDENI
- B. KENNEDY
- L. LONG
- B. MURPHY
- T. SUTHERLAND
- M. CLARK

FILE: B-850

MAY 8 8:41
USNRC REGION 3
ATLANTA, GEORGIA

DUKE POWER COMPANY
OCONEE NUCLEAR STATION
NRC NOTIFICATION OF REPORTABLE OCCURRENCE

REPORT NUMBER 269/79-13

TIME/DATE OF INCIDENT 0830 5/7/79 TIME/DATE OF DISCOVERY 0930 5/7/79

UNIT(S) 1 UNIT STATUS AT TIME OF INCIDENT ~18% F.P.

DESCRIPTION OF INCIDENT: Quadrant power tilt was beyond the error-adjusted steady-state limit (+3.5%) for more than (4) hours without resetting the Nuclear Overpower Trip Setpoints per Tech Spec 3.5.2.4.b.2 (- highest tilt ~+6.1% @ 1100 5/7/79)

HOW INCIDENT WAS DISCOVERED: Average power increases after Emergency Feedwater pump flow stability test.

IMMEDIATE CORRECTIVE ACTION: Reduced power below 15% E.P. to evaluate tilt.

REGULATORY DOCKET FILE COPY

REPORTABLE PURSUANT TO TECHNICAL SPECIFICATION 6.6.2.1.a (2)

DATE REPORT DUE TO NRC/OIE 5/21/79

TIME/DATE TELECOPIED OR OTHERWISE TRANSMITTED TO NRC/OIE 0830 5/8/79

PREPARED BY David J. Vito PHONE (803) 882-5363

REGULATORY DOCKET FILE COPY
7906140353

A002
5/10