

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 7908140581 DOC. DATE: 79/07/18 NOTARIZED: NO  
 FACIL: 50-269 Oconee Nuclear Station, Unit 1, Duke Power Co.  
 AUTH. NAME: PARKER, W.O. AUTHOR AFFILIATION: Duke Power Co.  
 RECIP. NAME: O'REILLY, J.P. RECIPIENT AFFILIATION: Region 2, Atlanta, Office of the Director

DOCKET #  
05000269

SUBJECT: Modifies statement made RO-269/78-27. Submitted on 790115 re potentially malfunctioning valves. FDW-47 & FDW-48 valves are no longer used.

DISTRIBUTION CODE: A002S COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1  
 TITLE: INCIDENT REPORTS

NOTES: M. CUNNINGHAM - ALL AMENDS TO FSAR & CHANGES TO TECH SPECS.

ACTION:	RECIPIENT ID CODE/NAME	COPIES		RECIPIENT ID CODE/NAME	COPIES	
		LTR	ENCL		LTR	ENCL
	05 BC ORB #4	4	1			
INTERNAL:	01 REG FILE	1	1	02 NRC PDR	1	1
	09 I&E	2	2	11 MPA	3	3
	14 TA/EDO	1	1	15 NOVAK/KNIEL	1	1
	16 EEB	1	1	17 AD FOR ENGR	1	1
	18 PLANT SYS BR	1	1	19 I&C SYS BR	1	1
	20 AD PLANT SYS	1	1	21 AD SYS/PROJ	1	1
	22 REAC SAFT BR	1	1	23 ENGR BR	1	1
	24 KREGER	1	1	25 PWR SYS BR	1	1
	26 AD/SITE ANAL	1	1	27 OPERA LIC BR	1	1
	28 ACCIDENT ANALYS	1	1	29 AUX SYS BR	1	1
	E JORDAN/IE	1	1	HANAUER, S.	1	1
	I&C SYS BR	1	1	TMI-H STREET	1	1
EXTERNAL:	03 LPDR	1	1	04 NSIC	1	1
	29 ACRS	16	16			

AUG 16 1979

*copy*  
*CCP*

TOTAL NUMBER OF COPIES REQUIRED: LTR 49 ENCL 0  
49

7902403L

*Headstart.*

DUKE POWER COMPANY

POWER BUILDING  
ATLANTA

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

JUL 23 10:09

WILLIAM O. PARKER, JR.  
VICE PRESIDENT  
STEAM PRODUCTION

July 18, 1979

TELEPHONE: AREA 704  
373-4083

Mr. James P. O'Reilly, Director  
U.S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, GA 30303

Re: Oconee Unit 1  
Docket No. 50-269

Dear Mr. O'Reilly:

My letter of January 15, 1979, transmitted to your office Reportable Occurrence Report RO-269/78-27. In the section entitled "Corrective Actions," it was noted that two potentially malfunctioning valves, valves FDW-47 and -48, would be examined at a later outage. On June 29, 1979, the two valves were examined, and it was determined that they were in proper working condition. It should be noted that since that time, operation of the emergency feed-water system has been modified such that these valves are no longer in use.

Very truly yours,

*William O. Parker, Jr.*  
William O. Parker, Jr. *By [Signature]*

SRL/sch

cc: Director, Office of Management Information  
and Program Control

*A002  
3/10*



7908140581 790373

ORIGINAL COPY