

*Central Filer*

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

August 30, 1979

WILLIAM O. PARKER, JR.  
VICE PRESIDENT  
STEAM PRODUCTION

TELEPHONE: AREA 704  
373-4083

79 SEP 5 11:23  
USNRC REGION II  
ATLANTA, GEORGIA

Mr. James P. O'Reilly, Director  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Re: RII: IPO  
50-269  
50-270  
50-287

Dear Mr. O'Reilly:

Please find attached Duke Power Company's responses to the concerns raised in Item 1 of IE Bulletin 79-17 as required by Item 5. The responses include the pre-service inspections, inservice inspections and a summary of the water chemistry control program for those stagnant systems potentially affected by intergranular stress corrosion cracking.

This response was due on August 24, 1979 but due to unanticipated administrative problems in copying the rather large amount of information requested the submittal was delayed to the above date.

Very truly yours,

*William O. Parker, Jr.*  
William O. Parker, Jr. *By [Signature]*

KRW:scs  
Attachment

cc: Director, Division of Operating Reactors  
Office of Inspection and Enforcement  
Washington, D. C. 20555

790479  
ORIGINAL COPY KB

7909280674

202