

Central File
50-269

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

AO/g

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

March 19, 1980

30 MAR 21 AIO: 38
TELEPHONE AREA 704
373-4083
SOUTH ATLANTA REGION


Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Re: Oconee Unit 1
Docket No. 50-269
IE Bulletin 79-13

Dear Sir:

My letter of February 25, 1980 provided documentation of the results of the radiographic examinations of the feedwater nozzle welds on Oconee Unit 1. Included was a draft of a report documenting a metallurgical evaluation of the indications reported. Please find attached a final copy of the report by Mr. Helmut Thielsch which was transmitted by his letter of March 13, 1980. The report concludes, as expected, that "The Feedwater piping at the "A" and "B" Riser Connection is suitable for continued service" and that, "Repair . . . would not improve further the acceptable level of integrity." It is therefore considered that Oconee Unit 1 has been evaluated in full compliance with IE Bulletin 79-13 and that no corrective actions are required.

Very truly yours,


William O. Parker, Jr.

KRW:scs

Attachments

8004100351