

*Central File*

USNRC REGION I  
**DUKE POWER COMPANY**

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

30 AUG 28 P 1: 33

WILLIAM O. PARKER, JR.  
VICE PRESIDENT  
STEAM PRODUCTION

August 22, 1980

TELEPHONE: AREA 704  
373-4083

Mr. James P. O'Reilly, Director  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Re: RII:JPO  
50-269, -270, -287

Dear Mr. O'Reilly:

Regarding IE Bulletin 80-19, Revision 1, which was transmitted by your letter of August 15, 1980, a review of the Oconee Nuclear Station (ONS) has indicated that C. P. Clare Model HG2X-1011 mercury-wetted relays are not used in the Reactor Protective System of any Oconee unit. Therefore, the subject bulletin is not applicable to ONS.

Per your request for estimated manpower expended in responding to this Bulletin, approximately 60 manhours were required to perform the review and report its results.

Very truly yours,

*William O. Parker, Jr.*  
William O. Parker, Jr. *By HAK*

FTP:scs

cc: Director  
Division of Reactor Operations Inspection  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

8009170 233

*Q*