NRC FORM 591M PART 1 U.S. NUCLEAR REGULATORY COMMIS					
10 CFR 2 201	FETY INSPECTION REPORT	AND COMPLIANCE INSPECTION			
 LICENSEE/LOCATION INSPEC Applied Technical Services, I 1049 Triad Court Marietta, GA 30062 Location Inspected: Louisville Jobsites REPORT NUMBER 	nc.	2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region I, 2100 Renaissance Blvd, Suite 100 King of Prussia, Pennsylvania 19406-2713			
3. DOCKET NUMBER	4. LICENSE NUMBER	5. DATES OF INSPECTION			
03038879	10-35278-01	Oct. 3, 4, 5 & 6; Nov. 16, 17, & Dec. 1, 2016			
LICENSEE:					
 The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The Inspection findings are as follows: Based on the inspection findings, no violations were identified. Previous violation(s) closed. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, to exercise discretion, were satisfied. Non-cited violation(s) were discussed involving the following requirement(s) and corrective action(s): 4. During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited in accordance with the NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11. (Violations and Corrective Actions) Violation and corrective actions listed on Page 2 of this record. 					
·	and a second				
Statement of Corrective Actions hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.					
Title	Printed Name	Signature Date			
LICENSEE'S REPRESENTATIVE	GARY WINKLER	2 Augelluelle 12/01/15			
NRC INSPECTOR	Scott Wilson	Rttfflu 12/01/2016			
BRANCH CHIEF	Blake Welling	plahe / 12/6/16			
NRC FORM 591M PART 1 (07-2012 SUNSI Review Completed By:) (RI Rev. 09/12/2013) SWilson	X Public X Non-Sensitive			

SUNSI Review Completed By:

SWilson 1 /

This document becomes an NRC Official Agency Record once it is signed by the Branch Chief

NRC FORM 591M PART 2 (07-2012) 10 CFR 2 201 SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION						
1. LICENSEE/LOCATION INSPECTED; 2. NRC/REGIONAL OFFICE						
Applied Technical Services, Inc. 1049 Triad Court Marietta, GA 30062 Location Inspected: Louisville, KY; Rockville, VA; Temp. Johsites REPORT NUMBER(S) 2016003		2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region I, 2100 Renaissance Blvd, Suite 100 King of Prussia, Pennsylvania 19406-2713				
3. DOCKET NUMBER(S)	KET NUMBER(S) 4. LICE		5. DATE(S) OF INSPECTION			
03038879		35278-01	Oct. 3, 4, 5 & 6; Nov. 16, 17, & Dec. 1, 2016			
 (Continued) 10 CFR 34.43(e) requires, in part, that the RSO or designee shall conduct an inspection program of the job performance of each radiographer and radiographer's assistant to ensure that the Commission's regulations, license requirements, and the applicant's operating and emergency procedures are followed. The inspection program must: (1) Include observation of the performance of each radiographer and radiographer's assistant during an actual industrial radiographic operation, at intervals not to exceed 6 months; Contrary to the above, Applied Technical Services, Inc.'s RSO or designee had not conducted an inspection program of the job performance of each radiographer to ensure that the Commission's regulations, license requirements, and the applicant's operating and emergency procedures were followed. Specifically, licensee documents indicated that on June 2, 3, 6, 7, 8, 9, 10, 13, 14, 15, and 16, 2016, a radiographer authorized by Applied Technical Services, Inc. conducted radiographic operations in exclusive Federal jurisdiction at NASA's Langley Research Center in Hampton, Virginia, and the radiographer had not been observed as part of the licensee's inspection program within the six month period prior as required by 10 CFR 34.43(e). The performance of the radiographer had last been observed by the RSO during an actual industrial radiographic operation on November 28, 2015. This is a Severity Level IV violation (Enforcement Policy Section 6.3). A telephonic exit meeting was held with the President of ATS and the Corporate RSO on December 1, 2016. During the exit meeting the Corporate RSO stated that the violation was an oversight on his part. As a corrective action, the RSO stated that the will implement a system of reminders to prevent this type of oversight in the future. 						
-END-						
RC FORM 591M PART 2 (07-2012)						

/