



Entergy Operations, Inc.
P. O. Box 756
Port Gibson, MS 39150

James Nadeau
Manager, Regulatory Assurance
Grand Gulf Nuclear Station
Tel. (601) 437-2103

GNRO-2016/00063
January 5, 2017

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, DC 20555-0001

SUBJECT: Licensee Event Report LER 2016-009-00, Entry into Mode of Applicability
with the OPRM Upscale Settings Incorrectly Set
Grand Gulf Nuclear Station, Unit 1
Docket No. 50-416
License No. NPF-29

Dear Sir or Madam:

Attached is Licensee Event Report LER 2016-009-00, Entry into Mode of Applicability with the Oscillation Power Range Monitor (OPRM) Upscale Settings incorrectly set. This report is being submitted in accordance with Title 10 Code of Federal Regulations 50.73(a)(2)(i)(B) and 10CFR50.73(a)(2)(v)(A).

This letter contains no new commitments. If you have any questions or require additional information, please contact James Nadeau at 601-437-2103.

Sincerely,

A handwritten signature in cursive script, appearing to read "James Nadeau".

JJN/ram

Attachment: Licensee Event Report (LER) 2016-009-00

cc: see next page

U.S. Nuclear Regulatory Commission
ATTN: Mr. Siva Lingam
Mail Stop OWFN 8 B1
Rockville, MD 20852-2738

NRC Senior Resident Inspector
Grand Gulf Nuclear Station
Port Gibson, MS 39150

U. S. Nuclear Regulatory Commission
ATTN: Marc L. Dapas (w/2)
Regional Administrator, Region IV
1600 East Lamar Boulevard
Arlington, TX 76011-4511



LICENSEE EVENT REPORT (LER)

(See Page 2 for required number of digits/characters for each block)

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Privacy and Information Collections Branch (T-5 F53), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME Grand Gulf Nuclear Station Unit 1	2. DOCKET NUMBER 05000416	3. PAGE 1 OF 2
--	-------------------------------------	--------------------------

4. TITLE
Entry into Mode of Applicability with the Oscillation Power Range Monitor Upscale Settings Incorrectly Set

5. EVENT DATE			6. LER NUMBER			7. REPORT DATE			8. OTHER FACILITIES INVOLVED	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REV NO.	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER
03	27	2016	2016	- 009	- 00	01	05	2017	N/A	05000N/A
									FACILITY NAME	DOCKET NUMBER
									N/A	05000N/A

9. OPERATING MODE MODE 1	11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check all that apply)									
	<input type="checkbox"/> 20.2201(b)		<input type="checkbox"/> 20.2203(a)(3)(i)		<input type="checkbox"/> 50.73(a)(2)(ii)(A)		<input type="checkbox"/> 50.73(a)(2)(viii)(A)			
	<input type="checkbox"/> 20.2201(d)		<input type="checkbox"/> 20.2203(a)(3)(ii)		<input type="checkbox"/> 50.73(a)(2)(ii)(B)		<input type="checkbox"/> 50.73(a)(2)(viii)(B)			
	<input type="checkbox"/> 20.2203(a)(1)		<input type="checkbox"/> 20.2203(a)(4)		<input type="checkbox"/> 50.73(a)(2)(iii)		<input type="checkbox"/> 50.73(a)(2)(ix)(A)			
10. POWER LEVEL 100%	<input type="checkbox"/> 20.2203(a)(2)(i)		<input type="checkbox"/> 50.36(c)(1)(i)(A)		<input type="checkbox"/> 50.73(a)(2)(iv)(A)		<input type="checkbox"/> 50.73(a)(2)(x)			
	<input type="checkbox"/> 20.2203(a)(2)(ii)		<input type="checkbox"/> 50.36(c)(1)(ii)(A)		<input checked="" type="checkbox"/> 50.73(a)(2)(v)(A)		<input type="checkbox"/> 73.71(a)(4)			
	<input type="checkbox"/> 20.2203(a)(2)(iii)		<input type="checkbox"/> 50.36(c)(2)		<input type="checkbox"/> 50.73(a)(2)(v)(B)		<input type="checkbox"/> 73.71(a)(5)			
	<input type="checkbox"/> 20.2203(a)(2)(iv)		<input type="checkbox"/> 50.46(a)(3)(ii)		<input type="checkbox"/> 50.73(a)(2)(v)(C)		<input type="checkbox"/> 73.77(a)(1)			
	<input type="checkbox"/> 20.2203(a)(2)(v)		<input type="checkbox"/> 50.73(a)(2)(i)(A)		<input type="checkbox"/> 50.73(a)(2)(v)(D)		<input type="checkbox"/> 73.77(a)(2)(i)			
	<input type="checkbox"/> 20.2203(a)(2)(vi)		<input checked="" type="checkbox"/> 50.73(a)(2)(i)(B)		<input type="checkbox"/> 50.73(a)(2)(vii)		<input type="checkbox"/> 73.77(a)(2)(ii)			
				<input type="checkbox"/> 50.73(a)(2)(i)(C)		<input type="checkbox"/> OTHER		Specify in Abstract below or in NRC Form 366A		

12. LICENSEE CONTACT FOR THIS LER

LICENSEE CONTACT James Nadeau, Manager Regulatory Assurance	TELEPHONE NUMBER (Include Area Code) 601-437-2103
--	--

13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX
A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

14. SUPPLEMENTAL REPORT EXPECTED <input checked="" type="checkbox"/> YES (If yes, complete 15. EXPECTED SUBMISSION DATE) <input type="checkbox"/> NO	15. EXPECTED SUBMISSION DATE	MONTH 5	DAY 31	YEAR 2017
--	-------------------------------------	------------	-----------	--------------

ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)

On March 27, 2016, the Entergy, while returning the GGNS Unit 1 to power operations at the conclusion of Refueling Outage 21, reactor thermal power was allowed to exceed 16.8 percent without first fully calibrating the Oscillation Power Range Monitor (OPRM) to include the new limits required by the adoption and implementation of the Maximum Extended Load Limit Line Plus (MELLLA+) operating range. Specifically, the OPRM Upscale setting requirements specified in Technical Specification 3.3.1.1, Reactor Protection System (RPS) Instrumentation, Table 3.3.1.1-1, Reactor Protection System Instrumentation, Function 2, Average Power Range Monitors, Sub-Function f. OPRM Upscale were not fully met. The direct cause of this event was the failure to ensure the required procedure changes were incorporated and performed prior to the unit entering the mode of applicability. Corrective actions included the addition of the condition to Limiting Condition for Operation tracking system to ensure resolution prior to a mode of applicability. This event is reportable as a licensee event report (LER) in accordance with 10CFR50.73(a)(2)(i)(B) as an operation or condition prohibited by Technical Specifications and 10CFR50.73(a)(2)(v)(A) for the loss of safety function.



**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Privacy and Information Collections Branch (T-5 F53), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME	2. DOCKET NUMBER	3. LER NUMBER		
		YEAR	SEQUENTIAL NUMBER	REV NO.
Grand Gulf Nuclear Station Unit 1	05000416	2016	- 009	- 00

NARRATIVE

On March 27, 2016, the Entergy, while returning the GGNS Unit 1 to power operations at the conclusion of Refueling Outage 21, reactor thermal power was allowed to exceed 16.8 percent without first fully calibrating the Oscillation Power Range Monitor (OPRM) to include the new limits required by the adoption and implementation of the Maximum Extended Load Limit Line Plus (MELLLA+) operating range. Specifically, the OPRM Upscale setting requirements specified in Technical Specification 3.3.1.1, Reactor Protection System (RPS) Instrumentation, Table 3.3.1.1-1, Reactor Protection System Instrumentation, Function 2, Average Power Range Monitors, Sub-Function f. OPRM Upscale were not fully met.

This error was subsequently discovered on November 17, 2016 during a review of General Electric Hitachi (GEH) Report 0000-0158-7807, Revision 0000, PRNM System DSS-CD Settings against the settings in GGNS Procedures 06-IC-1C51-R-0077A/B/C/D, Average Power Range Monitor Calibration.

REPORTABILITY

This event is reportable as a licensee event report (LER) in accordance with 10CFR50.73(a)(2)(i)(B) as an operation or condition prohibited by Technical Specifications and 10CFR50.73(a)(2)(v)(A) for the loss of safety function.

CAUSE

The causal evaluation for this event is ongoing and this LER will be supplemented upon completion of the causal analysis.

The direct cause of this event was the failure to ensure the required procedure changes were incorporated and performed prior to the unit entering the mode of applicability.

CORRECTIVE ACTIONS

Corrective actions included the addition of the condition to Limiting Condition for Operation tracking system to ensure resolution prior to a mode of applicability.

The condition has been added to Limiting Condition for Operation for tracking ensure resolution prior to restart.

SAFETY SIGNIFICANCE

There were no actual nuclear safety consequences or radiological consequences as a result of this calibration error. No Technical Specification Safety Limits were violated.

PREVIOUSLY SIMILAR EVENTS

LER 2013-006-00, Primary Containment Inoperable Due to an Inadequate Surveillance Procedure Resulting in a Loss of Safety Function

The causes and corrective actions implemented as a result of LER 2013-006-00 were reviewed and it has been determined that the corrective actions were acceptable and could not have prevented the event documented in this LER.