

November 12, 1973

Richard I. Goldsmith, Esq.
Syracuse University
College of Law
E. I. White Hall, Campus
Syracuse, New York 13210

In the Matter of Niagara Mohawk Power Corporation
(Nine Mile Point, Unit No. 2)
Docket No. 50-410

Dear Mr. Goldsmith:

Enclosed is a copy of a letter dated October 30, 1973, from the staff (Regulatory Operations) which refers to an inspection of activities relating to the construction permit application filed in this proceeding.

As indicated in the enclosed letter, the staff's Inspection Report will ultimately be placed in the Public Document Room. Should you desire a copy of the report, I will be pleased to forward same to you, upon request, at the appropriate time.

Additionally, I might note that the findings set forth in the Inspection Report were summarized during the course of testimony in the referenced proceeding given by Messrs. William M. Hayward and Joseph H. Tillou on October 17, 1973, (see tr. pp.1002-1014).


Sincerely,

Bernard M. Bordenick
Counsel for AEC Regulatory Staff

Enclosure:
Cy. of staff ltr. dtd 10/30/73

cc: See page 2

OFFICE ▶						hearing
SURNAME ▶						
DATE ▶						



Richard I. Goldsmith, Esq.

- 2 -

cc w/enclosure:


Daniel M. Head, Esq.
 Dr. Marvin M. Mann
 Dr. William E. Martin
 Eugene B. Thomas, Jr., Esq.
 Joseph F. Tubridy, Esq.
 Mr. Gustave A. Linenberger
 Mr. J. Bruce MacDonald
 Arvin E. Upton, Esq.


James P. McGranery, Jr., Esq.
 Ms. Suzanne Weber
 Atomic Safety and Licensing
 Board Panel
 Atomic Safety and Licensing
 Appeal Board
 Mr. Frank W. Karas

Distribution:

Bordenick
 Cohen
 Massar
 Shapar
 Engelhardt
 A.Bournia-DL
 J.Norris-EP
 OGC Files
 REG Central
 PDR
 LPDR

OFFICE ▶	OGC <i>BMS</i>				
SURNAME ▶	Bordenick: am Massar <i>MA</i>				
DATE ▶	11/12/73				






OCT 30 1973

-2-

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,



R. F. Heishman, Acting Chief
Facilities Construction and
Engineering Support Branch

Enclosure:

RO Inspection Report No. 50-410/73-02



27. 2