

## TELECOPY MESSAGE

To: 215-347-5000 ext 247 FAX: 215-347-2110 ext DATE/TIME 10/26/78 10:35

Telephone Number

Telephone Number

TO: BOYCE H. GRIER  
Director of Regulatory Operation  
USNRC Region I  
631 Park Avenue  
King of Prussia, PA. 19406

From: Niagara Mohawk Power Corporation  
Nine Mile Point Nuclear Station  
Unit #1  
P.O. Box #32  
Lycoking, New York 13093

SUBJECT: PROPT REPORTABLE OCCURRENCE  
DOCKET NO. 50-220 LICENSE NO. DPR-63  
ASSIGNED LER NO. 78- 36

EVENT DATE: 10/25/78 REPORT DATE: 10/26/78

EVENT DESCRIPTION: Analysis of September's Proportional Composite found that concentrations of sodium and sulfate exceeded the values for maximum increase over lake ambient concentration specified in Table 2.3-1 in Environmental Technical Specifications.

COMPONENTS INVOLVED: Make-up Demineralizer Waste Tank, Flow Control Discharge Valve, Flow Meters

CAUSE AND REMEDIAL ACTION: Waste tanks were discharged at rates which exceeded the maximum calculated rate on the discharge data sheets. This was due to a failure of the flow meter on the discharge line, and attempts to control discharge rate by manually throttling the discharge valve. As of October 10, 1978 a newly designed flow control system has been installed, permitting accurate control of discharge meter. In addition, more timely review of discharge records has been established.

- FACILITY STATUS:  INERTIAL  91
- c) Routine Startup
  - d) Routine Shutdown
  - e) Steady State Oper  X
  - f) Load Change
  - g) Shutdown
  - h) Refueling
  - i) Other
  - j) Not Applicable

A written follow-up report will be sent within ten days.

TELECOPY TO

B. H. GRIER

NAME

FROM T.J. Perkins

NAME

DATE 10/26/78

7811130400

08 FEB 9