APPENDIX A

NOTICE OF VIOLATION

Niagara Mohawk Power Corporation

Docket No. 50-220

Based on the results of an NRC inspection conducted on December 11-14, 1978, it appears that one of your activities was not conducted in full compliance with the conditions of your NRC Facility License No. DPR 63 as indicated below. This item is a deficiency.

Technical Specification 6.8.1 states in part: "Written procedures and administrative policies shall be established, implemented and maintained..." and,

Technical Specification 6.8.2 states in part: "Each procedure... of 6.8.1 above, ...shall be reviewed by the SORC and approved by the General Superintendent Nuclear Generation prior to implementation..."

Contrary to the above, on November 9-10, 1978, a Station Shift Supervisor Instruction established and implemented a procedure to cross-connect the fire protection systems of Nine Mile Point Unit 1 with Nine Mile Point Unit 2. This procedure was not reviewed by the SORC and approved by the General Superintendent Nuclear Generation prior to implementation.

TO A REPORT OF THE

•

. ·

,

•

.