



REGULATORY OPERATIONAL REPORT SUBMISSION

TELETYPE MESSAGE

TO: 015-337-5774 FROM: 015-343-260 X 1342 DATE/TIME 5/23/79 / 3:25p
 Telephone Number Telephone Number
94-7359

TO: RONALD M. GRIGG, Director of Regulatory Operations, USNRC Region I, 631 Park Avenue, King of Prussia, PA. 19406
 From: Niagara Mohawk Power Corporation, One Mile Point Nuclear Station, Unit #1, P.O. Box #32, Lyncburg, New York 13093.

SUBJECT: PROMPT REPORTABLE OCCURRENCE
 BUREAU NO. 50-220 LICENSE NO. NPS-63
 ASSIGNED LER NO. 79-12

EVENT DATE: 5/23/79 REPORT DATE: _____

EVENT DESCRIPTION:

During inspection, a number of concrete anchor bolts were found to be loose or improperly installed.

COMPONENTS INVOLVED:

Concrete Anchor Bolts

CAUSE AND CORRECTIVE ACTION:

A pull-test program has been implemented and deficiencies will be repaired or replaced. Loose bolts are being tightened during inspection.

FACILITY STATUS:

NORMAL _____

- c) Routine Startup _____
- d) Routine Shutdown _____
- e) Steady State Oper _____
- f) Load Change _____
- g) Startdown _____
- h) Refueling _____
- i) Other _____
- j) Not Applicable _____

A written follow-up report will be sent within two weeks.

TELETYPE TO R.H. Grier FROM T.J. Perkins DATE 5/23/79
DATE DATE
R.R. Schneider

7906010214

Acc 5/30

54