

NIAGARA MOHAWK POWER CORPORATION/300 ERIE BOULEVARD WEST, SYRACUSE, N.Y. 13202/TELEPHONE (315) 474-1511

September 11, 1980

Mr. Boyce H. Grier, Director
Office of Inspection and Enforcement
United States Nuclear Regulatory
Commission - Region I.
631 Park Avenue
King of Prussia, Pennsylvania 19406

RE: Docket No. 50-220
I.E. Bulletin 80-20, Revision 1

Dear Mr. Grier:


Your July 31, 1980, Inspection and Enforcement Bulletin 80-20 requested actions regarding failures of Westinghouse Type W-2 Spring Return Control Switches in safety related systems at Nine Mile Point Unit #1. The following addresses Item 1 of that Bulletin.

Investigations have concluded that presently there are no switches of the type or application described in the Bulletin at this station. An estimate of manpower expended to conduct the review and report preparation is 8 man hours.


Actions described herein complete response requirements for this Bulletin. Any additional information or records are readily available at your request.

The information contained in this letter demonstrates that continued operation of Nine Mile Point Unit #1 does not present an undue safety hazard to the public.

Very truly yours,


James Bartlett
Executive Vice President

jl/
xc: NRC Office of Inspection and Enforcement
Division of Reactor Operations Inspection
Washington, D. C. 20555



8010010 852



