

U.S. NUCLEAR REGULATORY COMMISSION
REGION I

Report Nos. 50-220/87-09
50-410/87-19

Docket Nos. 50-220
50-410

License Nos. DPR-63
CPPR-112

Licensee: Niagara Mohawk Power Corporation
300 Erie Boulevard West
Syracuse, New York 13202

Facility Name: Nine Mile Point, Units 1 and 2

Inspection At: Scriba, New York

Inspection Conducted: June 10-11, 1987

Type of Inspection: Routine, Announced Physical Security Inspection

Inspectors: for Roland J. Bailey 8-10-87
W. G. Martin, Physical Security Inspector date

for Roland J. Bailey 8-10-87
W. K. Lancaster, Physical Security Inspector date

Approved by: W. R. Keimig 8/10/87
R. R. Keimig, Chief, Safeguards Section, DRSS date

Inspection Summary: Routine, Announced Physical Security Inspection on
June 10-11, 1987 (50-220/87-09 and 50-410/87-19)

Areas Inspected: Security and Safeguards Contingency Plan; Physical Barriers
(Protected and Vital Areas) and Training and Qualification Plan.

Results: The licensee was in compliance with NRC requirements in the areas
examined.



DETAILS

1. Persons Contacted

J. P. Beratta, Supervisor, Nuclear Security
D. K. MacVittie, Nuclear Security Specialist
D. O'Hara, Assistant Nuclear Security Specialist
C. A. Boniti, Supervisor of Training, Nuclear Security
E. E. Croucher, Firearms Instructor
J. A. Dilk, Training Instructor, Nuclear Security
W. A. Mittag, Training Instructor, Nuclear Security
J. A. Dilk, Training Instructor, Nuclear Security
F. L. Laifer, Training Instructor, Nuclear Security
D. M. Pierce, Training Instructor, Nuclear Security

The inspectors also interviewed other licensee personnel including members of the proprietary security force.

2. Security Plan and Implementing Procedures

The inspectors reviewed the NRC-approved security plan and implementing procedures including changes contained in Plan Revision 2. Plan Revision 2 was submitted by the licensee under 10 CFR 50.54(p) on April 24, 1987 and subsequently accepted by Region I on June 17, 1987. The procedures were adequate and appropriate to implement the NRC-approved security plan.

3. Physical Barriers (Protected Area)

The inspectors observed that the licensee maintained the barrier surrounding the protected area in accordance with the NRC-approved security plan. The licensee recently installed a second fence along the lake front protected area perimeter of Unit 1, thus completing a double fence barrier along the lake front for both units.

4. Access Control (Personnel)

The inspectors observed that the licensee's access control and badging system was in accordance with the NRC-approved security plan and that all personnel entering the Protected Area were properly searched for unauthorized material. The search equipment was functioning properly and is adequate and appropriate for its intended purpose.

5. Security Contingency Plan Implementation Review

The inspectors reviewed the licensee's NRC-approved Security Contingency Plan, including Revision 2. The licensee's program, as outlined in the NRC-approved plan, was adequate. There remains, however, a lack of participation by the operations organization in the contingency drills conducted by the security organization. It was also noted that the



security organization has only minor involvement during full-scale site emergency exercises, including the exercise planned for June, 1987. The inspectors addressed and expressed concern over these matters in discussions with security management who assured that actions would be taken to increase participation of each organization, in each case.

6. Training and Qualifications Plan

The licensee is planning numerous changes to the training and qualifications plan to delete redundant requirements, incorporate new law enforcement techniques, delete unnecessary or non-security related tasks, and combine security related tasks to reduce the total number of tasks. These changes will be reviewed when the licensee submits a revision to the Plan to the NRC under 10 CFR 50.54(p), in the near future..

7. Exit Interview

The inspectors met with the licensee personnel listed in Paragraph 1 at the conclusion of the inspection on June 11, 1987. At that time the purpose, scope, and findings of the inspection were presented to the licensee by the inspectors.

Written material was not provided to the licensee by the inspector at any time during the inspection.

