



UNITED STATES
NUCLEAR REGULATORY COMMISSION
WASHINGTON, D. C. 20555

June 23, 1993

Docket No. 50-410

Mr. B. Ralph Sylvia
Executive Vice President, Nuclear
Niagara Mohawk Power Corporation
301 Plainfield Road
Syracuse, New York 13212

Dear Mr. Sylvia:

SUBJECT: NINE MILE POINT NUCLEAR STATION, UNIT 2 - RESPONSE TO NRC
BULLETIN 93-02, "DEBRIS PLUGGING OF EMERGENCY CORE COOLING SUCTION
STRAINERS" (TAC NO. M86587)

This letter acknowledges receipt of Niagara Mohawk Power Corporation's (NMPC's) response dated June 10, 1993, to NRC Bulletin 93-02 (Bulletin). The Bulletin was issued May 11, 1993, to all nuclear power reactor licensees. It requested licensees to identify fibrous material in the primary containment, take any necessary compensatory measures, and remove any such material. NMPC's response stated that no fibrous filter material or other temporary sources of fibrous material, such as described in the Bulletin, were identified as being installed or stored in the containment. Based on that, we consider your actions to be complete. Please retain any records of your actions in response to this Bulletin, as subsequent inspection activities may be conducted in regards to this issue.

Should you have any questions, please contact me at (301) 504-1406 or the Lead Project Manager for this issue, John B. Hickman at (301) 504-3017.

Sincerely,

John E. Menning, Project Manager
Project Directorate I-1
Division of Reactor Projects - I/II
Office of Nuclear Reactor Regulation

cc: See next page

250072

9306280251 930623
PDR ADOCK 05000410
Q PDR

AD1
JF01
110
NRC FILE CENTER COPY



100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000

Mr. B. Ralph Sylvia
Niagara Mohawk Power Corporation

Nine Mile Point Nuclear Station
Unit No. 2

cc:

Mark J. Wetterhahn, Esquire
Winston & Strawn
1400 L Street, NW.
Washington, DC 20005-3502

Regional Administrator, Region I
U. S. Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, PA 19406

Mr. Richard Goldsmith
Syracuse University
College of Law
E. I. White Hall Campus
Syracuse, New York 12223

Charles Donaldson, Esquire
Assistant Attorney General
New York Department of Law
120 Broadway
New York, New York 10271

Resident Inspector
Nine Mile Point Nuclear Station
P. O. Box 126
Lycoming, New York 13093

Mr. Richard M. Kessel
Chair and Executive Director
State Consumer Protection Board
99 Washington Avenue
Albany, New York 12210

Gary D. Wilson, Esquire
Niagara Mohawk Power Corporation
300 Erie Boulevard West
Syracuse, New York 13202

Mr. Martin J. McCormick Jr.
Plant Manager, Unit 2
Nine Mile Point Nuclear Station
Niagara Mohawk Power Corporation
P. O. Box 32
Lycoming, New York 13093

Mr. David K. Greene
Manager Licensing
Niagara Mohawk Power Corporation
301 Plainfield Road
Syracuse, New York 13212

Mr. Neil S. Carns
Vice President - Nuclear Generation
Nine Mile Point Nuclear Station
Niagara Mohawk Power Corporation
P. O. Box 32
Lycoming, New York 13093

Ms. Donna Ross
New York State Energy Office
2 Empire State Plaza
16th Floor
Albany, New York 12223

Supervisor
Town of Scriba
Route 8, Box 382
Oswego, New York 13126



June 23, 1993

Docket No. 50-410

Mr. B. Ralph Sylvia
Executive Vice President, Nuclear
Niagara Mohawk Power Corporation
301 Plainfield Road
Syracuse, New York 13212

Distribution:

Docket File	CVogan
NRC & Local PDRs	JMenning
PDI-1 Reading	OGC
SVarga	ACRS (10)
JCalvo	CCowgill, RI
RACapra	JHickman, 13D1
RBarrett, 8H7	

Dear Mr. Sylvia:

SUBJECT: NINE MILE POINT NUCLEAR STATION, UNIT 2 - RESPONSE TO NRC
BULLETIN 93-02, "DEBRIS PLUGGING OF EMERGENCY CORE COOLING SUCTION
STRAINERS" (TAC NO. M86587)

This letter acknowledges receipt of Niagara Mohawk Power Corporation's (NMPC's) response dated June 10, 1993, to NRC Bulletin 93-02 (Bulletin). The Bulletin was issued May 11, 1993, to all nuclear power reactor licensees. It requested licensees to identify fibrous material in the primary containment, take any necessary compensatory measures, and remove any such material. NMPC's response stated that no fibrous filter material or other temporary sources of fibrous material, such as described in the Bulletin, were identified as being installed or stored in the containment. Based on that, we consider your actions to be complete. Please retain any records of your actions in response to this Bulletin, as subsequent inspection activities may be conducted in regards to this issue.

Should you have any questions, please contact me at (301) 504-1406 or the Lead Project Manager for this issue, John B. Hickman at (301) 504-3017.

Sincerely,

Original signed by:

John E. Menning, Project Manager
Project Directorate I-1
Division of Reactor Projects - I/II
Office of Nuclear Reactor Regulation

cc: See next page

LA:PDI-1	PM:PDI-1	D:PDI-1			
CVogan <i>CV</i>	JMenning <i>JM</i>	RACapra <i>RC</i>			
6/23/93	6/23/93	6/23/93	/ /	/ /	/ /

OFFICIAL RECORD COPY
FILENAME: NM286587.LTR

