

ACCELERATED DOCUMENT DISTRIBUTION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9307190054 DOC. DATE: 93/07/07 NOTARIZED: NO DOCKET #
 FACIL: 59-220 Nine Mile Point Nuclear Station, Unit 1, Niagara Powe 05000220
 AUTH. NAME AUTHOR AFFILIATION
 DAHLBERG, K.S. Niagara Mohawk Power Corp.
 RECIPIENT NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: Forwards LER 93-002-01 re automatic reactor scram on high neutron flux signal received during surveillance. Suppl submitted to describe main turbine tripping 10 s after full reactor scram.

DISTRIBUTION CODE: IE22T COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 147
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

	RECIPIENT ID CODE/NAME	COPIES	LTR	ENCL	RECIPIENT ID CODE/NAME	COPIES	LTR	ENCL
	PDI-1 LA	1	1		PDI-1 PD	1	1	
	BRINKMAN, D.	1	1					
INTERNAL:	ACNW	2	2		ACRS	2	2	
	AEOD/DOA	1	1		AEOD/DSP/TPAB	1	1	
	AEOD/ROAB/DSP	2	2		NRR/DE/EELB	1	1	
	NRR/DE/EMEB	1	1		NRR/DORS/OEAB	1	1	
	NRR/DRCH/HHFB	1	1		NRR/DRCH/HICB	1	1	
	NRR/DRCH/HOLB	1	1		NRR/DRIL/RPEB	1	1	
	NRR/DRSS/PRPB	2	2		NRR/DSSA/SPLB	1	1	
	NRR/DSSA/SRXB	1	1		REG FILE 02	1	1	
	RES/DSIR/EIB	1	1		RGNI FILE 01	1	1	
EXTERNAL:	EG&G BRYCE, J.H	2	2		L ST LOBBY WARD	1	1	
	NRC PDR	1	1		NSIC MURPHY, G.A	1	1	
	NSIC POORE, W.	1	1		NUDOCS FULL TXT	1	1	

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 504-2065) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!





NIAGARA MOHAWK POWER CORPORATION/Nine Mile Point Nuclear Station Unit #1, P.O. Box 32, Lycoming, NY 13093

Kim A. Dahlberg
Plant Manager

(315) 349-2443
(315) 349-2640 (FAX)

July 7 , 1993
NMP88382

United States Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

RE: Docket No. 50-220
LER 93-02, Supplement 1

Gentlemen:

In accordance with 10 CFR 50.73(a)(2)(iv), we are submitting LER 93-02, Supplement 1, "Automatic Reactor Scram on High Neutron Flux Signal Received During Surveillance Testing Due to Personnel Error." This supplement is being submitted to describe why the main turbine tripping 10 seconds after the full reactor scram is a correct plant response.

A 10 CFR 50.72(b)(2)(ii) report was made at 0956 hours on January 26, 1993, and LER 93-02 was originally submitted on February 24, 1993.

Very truly yours,

K. A. Dahlberg
Plant Manager - NMP1

KAD/JTP/lmc
ATTACHMENT

cc: Mr. Thomas T. Martin, Regional Administrator, Region I
Mr. Wayne L. Schmidt, Senior Resident Inspector

9307190054 930707
PDR ADDCK 05000220
S PDR



IFD
11

