CATEGORY 1

REGULATO INFORMATION DISTRIBUTION

STEM (RIDS)

。 ን ፡

ACCESSION NBR:9706060089 DOC.DATE: 97/05/30 NOTARIZED: NO DOCKET # FACIL:50-410 Nine Mile Point Nuclear Station, Unit 2, Niagara Moha 05000410 AUTH.NAME AUTHOR AFFILIATION

ABBOTT, R.B. Niagara Mohawk Power Corp. RECIP.NAME RECIPIENT AFFILIATION

Document Control Branch (Document Control Desk)

SUBJECT: Forwards corrected page 11, consisting of added words,
"...Engineering evaluation, nor repair, nor replacement as
Code justification for continued svc" to second sentence
last paragraph of ISI Summary Rept 950602-961102.

DISTRIBUTION CODE: A047D COPIES RECEIVED:LTR ENCL SIZE: + TITLE: OR Submittal: Inservice/Testing/Relief from ASME Code - GL-89-04

NOTES:

	RECIPIENT ID CODE/NAME PD1-1 LA HOOD,D	COPII LTTR 1 1	ESÉ ENCL 1	RECIPIENT ID CODE/NAME PD1-1 PD	COP: LTTR 1	IES ENCL 1
INTERNAL:		1	1	AEOD/SPD/RAB	1	1
	FILE CENTER OF	1	1	NRR/DE/EMEB	1	1
	NUDUCS-ABSTRACT	1	1	OGC/HDS3	1	0
	RES/DET/EIB	1	1	RES/DET/EMMEB	1	1
EXTERNAL:	LITCO ANDERSON	1	1	NOAC	1	1
	NRC PDR	1	1	•		*

NOTE TO ALL "RIDS" RECIPIENTS:
PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
ROOM OWFN 5D-5(EXT. 415-2083) TO ELIMINATE YOUR NAME FROM
DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

C

Α

Т

E

G

О

R

Y

1

D

U

M

E

N

T



GENERATION BUSINESS GROUP NINE MILE POINT NUCLEAR STATION/LAKE ROAD, P.O. BOX 63, LYCOMING, NEW YORK 13093/TELEPHONE (315) 349-1812 FAX (315) 349-4417

> May 30, 1997 NMP2L 1707

RICHARD B. ABBOTT Vice President and General Manager - Nuclear

U. S. Nuclear Regulatory Commission

Attn: Document Control Desk

Washington, DC 20555

Nine Mile Point Unit 2 RE:

Docket No. 50-410

NPF-69

Subject:

Inservice Inspections (ISI) Summary Report - Correction

Gentlemen:

On January 31, 1997, Niagara Mohawk Power Corporation submitted the Nine Mile Point Unit 2 ISI Summary Report for inservice inspections conducted between June 2, 1995 and November 2, 1996. This submittal was made to satisfy the requirements of American Society of Mechanical Engineers Boiler and Pressure Vessel Code Section XI. Following submittal, an editorial error was identified on page 11 of the Summary Report. Accordingly, a corrected page 11 is attached to this letter. This correction consists of adding the words "... Engineering evaluation, nor repair, nor replacement as the Code justification for continued service" to the second sentence, last paragraph on the subject page. We apologize for any inconvenience this error may have caused you.

Very truly yours.

Richard B. Abbott

Vice President and General Manager - Nuclear

RBA/JMT/lmc Attachment

Mr. H. J. Miller, Regional Administrator, Region I xc:


Mr. A. W. Dromerick, Acting Director, Project Directorate I-1, NRR

Mr. D. S. Hood, Senior Project Manager, NRR

05001 Mr. B. S. Norris, Senior Resident Inspector Records Management



']] AUI



length of RWCU piping. This length of piping will be examined during our sixth refueling outage scheduled to begin in May, 1998.

One hundred percent of all ISI pressure boundary examinations performed for RFO-5 were accepted by examination. That is to say, they met the Code's initial, conservative inspection criteria and required neither Engineering evaluation, nor repair, nor replacement as the Code justification for continued service. Over 99% of all ISI examinations of supports performed for Cycle-5 were likewise accepted by examination, with the balance being accepted by evaluation. Based on these facts, it is reasonable to conclude that the Code systems have been maintained and continue to function within the design envelope.

enc. NIS-1 Data Report (1) NIS-2 Data Reports (89)

