

# CATEGORY 1

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9802130056    DOC.DATE: 98/01/30    NOTARIZED: NO    DOCKET #  
FACIL: 50-410 Nine Mile Point Nuclear Station, Unit 2, Niagara Moha    05000410  
AUTH.NAME    AUTHOR AFFILIATION  
DAHLBERG, K.A.    Niagara Mohawk Power Corp.  
RECIP.NAME    RECIPIENT AFFILIATION  
Document Control Branch (Document Control Desk)

SUBJECT: Forwards LER 97-005-01 re high pressure core spray sys inoperable, due to failed unit cooler. Suppl contains info on failure analysis performed on custom termination modules & addl corrective action being taken.

DISTRIBUTION CODE: IE22T    COPIES RECEIVED: LTR 1 ENCL 1    SIZE: 144  
TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

### NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTR ENCL
	PD1-1 PD	1 1	HOOD, D	1 1
INTERNAL:	ACRS	1 1	AEOD/SPD/RAB	2 2
	AEOD/SPD/RRAB	1 1	FILE CENTER	1 1
	NRR/DE/ECGB	1 1	NRR/DE/EELB	1 1
	NRR/DE/EMEB	1 1	NRR/DRCH/HHFB	1 1
	NRR/DRCH/HICB	1 1	NRR/DRCH/HOLB	1 1
	NRR/DRCH/HQMB	1 1	NRR/DRPM/PECB	1 1
	NRR/DSSA/SPLB	1 1	NRR/DSSA/SRXB	1 1
	RES/DET/EIB	1 1	RGN1 FILE 01	1 1
EXTERNAL:	L ST LOBBY WARD	1 1	LITCO BRYCE, J H	1 1
	NOAC POORE, W.	1 1	NOAC QUEENER, DS	1 1
	NRC PDR	1 1	NUDOCS FULL TXT	1 1

### NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL DESK (DCD) ON EXTENSION 415-2083

FULL TEXT CONVERSION REQUIRED  
TOTAL NUMBER OF COPIES REQUIRED: LTR 25 ENCL 25

C  
A  
T  
E  
G  
O  
R  
Y  
  
1  
  
D  
O  
C  
U  
M  
E  
N  
T

AD4





NIAGARA MOHAWK

GENERATION  
BUSINESS GROUP

NINE MILE POINT NUCLEAR STATION/LAKE ROAD, P.O. BOX 63, LYCOMING, NEW YORK 13093

January 30, 1998  
NMP2L 1751

United States Nuclear Regulatory Commission  
Attn: Document Control Desk  
Washington, DC 20555

RE: Docket No. 50-410  
LER 97-05, Supplement 1

Gentlemen:

In accordance with 10CFR50.73 (a)(2)(v), we are submitting LER 97-05, Supplement 1, "High Pressure Core Spray System Inoperable Due to Failed Unit Cooler". This supplement contains the information on the failure analysis performed on Custom Termination Modules and an additional corrective action being taken.

Very truly yours,

Kim A. Dahlberg  
Plant Manager - NMP2

KAD/GJG/lmc  
Attachment

cc: Mr. H. J. Miller, Regional Administrator, Region I  
Mr. B. S. Norris, Senior Resident Inspector  
Records Management

*IE22%*

9802130056 980130  
PDR ADOCK 05000410  
S PDR



