

NORMAN W. CURTIS
Vice President-Engineering & Construction
821-5381

July 3, 1980

Mr. Boyce H. Grier
Director, Region I
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pennsylvania 19406

SUSQUEHANNA STEAM ELECTRIC STATION
UPDATE IN THE STATUS OF A DEFICIENCY ON
PACIFIC CHECK VALVES
ERS 100450/100508 FILE 840-4/900-10
PLA-502

Reference: PLA-466 of March 31, 1980

Dear Mr. Grier:

This supplements the above referenced correspondence and provides an update of the information provided in our PLA-466.

Unanticipated problems with check valve operation in the Unit I Core Spray pump discharge vertical pipe run will necessitate rework of the existing bonnet stops. Bechtel NCR 5913 documents this latest discrepancy. The original problem remains open under MCR 1-47.

We expect to provide a final report to the Commission by September, 1980.

Very truly yours,



N. W. Curtis
Vice President-Engineering & Construction-Nuclear

FLW:jmk

8009080 6:54

Mr. Boyce H. Grier

- 2 -

June 27, 1980

cc: Mr. Victor Stello (15) copies
Director-Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. G. McDonald, Director (1)
Office of Management Information & Program Control
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. Robert M. Gallo
U. S. Nuclear Regulatory Commission
P. O. Box 52
Shickshinny, Pennsylvania 18655

1-2-2000

11
6



11

11

11

11

11-2-2000