

NORMAN W. CURTIS
Vice President-Engineering & Construction
821-5381

SEP 30 1980

x0/2

Mr. Boyce H. Grier, Director
Region I
U.S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406

SUSQUEHANNA STEAM ELECTRIC STATION
IE BULLETIN 80-16
ER 100450 FILE 840-4
PLA-548

DOCKET NOS. 50-387
AND 50-388

Dear Mr. Grier:

This is a partial response to IE Bulletin 80-16, "Potential Misapplication of Rosemount Inc. Models 1151 and 1152 Pressure Transmitters with either 'A' or 'D' Output Codes."

IE Bulletin actions to be taken:

1. The subject pressure transmitters have been installed at Susquehanna in safety-related applications.
2. Two systems have so far been identified where these transmitters could be exposed to excessive input pressures:
 - a) Containment Pressure Indication (CPI) System
 - b) MSIV - Leakage Control System

Analyses of effects of transmitter maloperation are in progress.

- | | |
|---|--------------------|
| 3. Corrective actions: | Schedule |
| a) Replace subject transmitters in the CPI System | Prior to Fuel Load |
| b) Complete analysis to determine if any other systems are subject to this bulletin | October 20, 1980 |
| c) Complete analysis of effects of transmitter maloperation and determine additional corrective actions, if required. | December 5, 1980 |

8010240045

Q

R

Mr. Boyce H. Grier

Page 2

SEP 30 1980

Estimated manpower expended on IE Bulletin 80-16 will be provided in our final report which will be submitted by December 19, 1980.

Very truly yours,



N. W. Curtis

RMH:mks

cc: Director
Office of Inspection and Enforcement
Division of Reactor Construction Inspection
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. R. M. Gallo
U. S. Nuclear Regulatory Commission
P.O. Box 52
Shickshinny, PA 18655